



Site Classification Report
Ibis Place, Kurrajong Estate Stage 6,
Scone NSW 2337

Prepared for: McCloy Group Pty Ltd
EP4090.001 11 April 2025



Site Classification Report

Ibis Place, Kurrajong Estate Stage 6, Scone NSW 2337

McCloy Group Pty Ltd
Suite 2/317 Hunter Street
Newcastle 2300

11 April 2025

Our Ref: EP4090.001

LIMITATIONS

This Site Classification Report was conducted on the behalf of McCloy Group Pty Ltd for the purpose/s stated in **Section 1**.

EP Risk has prepared this document in good faith, but is unable to provide certification outside of areas over which EP Risk had some control or were reasonably able to check. The report also relies upon information provided by third parties. EP Risk has undertaken all practical steps to confirm the reliability of the information provided by third parties and do not accept any liability for false or misleading information provided by these parties.

It is not possible in a Site Classification Report to present all data, which could be of interest to all readers of this report. Readers are referred to any referenced investigation reports for further data.

Users of this document should satisfy themselves concerning its application to, and where necessary seek expert advice in respect to, their situation.

All work conducted and reports produced by EP Risk are based on a specific scope and have been prepared for McCloy Group Pty Ltd and therefore cannot be relied upon by any other third parties unless agreed in writing by EP Risk.

The report(s) and/or information produced by EP Risk should not be reproduced and/or presented/reviewed except in full.

QUALITY CONTROL

Version	Author	Date	Reviewer	Date	Quality Review	Date
v01	J. Aguirre/O. Pruteanu	08/04/2025	J. Young	11/04/2025	O. Pruteanu	11/04/2025

DOCUMENT CONTROL

Version	Date	Reference	Submitted to
v01	11/04/2025	EP4090.001	McCloy Group Pty Ltd



Brisbane
310 Edward Street
Brisbane QLD 4000
T 07 3506 0233
W www.eprisk.com.au

Newcastle
3/19 Bolton Street
Newcastle NSW 2300
T 02 4048 2845

Sydney
L13, 80 Mount Street
North Sydney NSW 2060
T 02 9922 5021

Melbourne
Unit 22/1 Ricketts Road
Mount Waverley VIC 3149
T 03 7504 3610
ABN 81 147 147 591

Table of Contents

1	Introduction	1
1.1	Objectives and Scope	1
2	Site Location and Description	2
3	Desktop Study	3
3.1	Regional Geology	3
3.2	Soil Landscape	4
3.3	Mine Subsidence	4
3.4	Acid Sulphate Soils (ASS)	4
4	Geotechnical Investigation	5
4.1	Investigation Methodology	5
4.2	Subsurface Profile	5
4.3	Groundwater	6
4.4	Laboratory Results	7
4.4.1	Shrink Swell	7
5	Preliminary Site Classification	8
5.1	Footings	10
5.1.1	High Level Footings	10
5.1.2	Piered Footings	10
6	References	11

List of Tables in Body of Report

Table 1.	Observed Geotechnical Units.....	5
Table 2.	Distribution of Subsurface Geological units Across the Investigated Locations	6
Table 3.	Shrink-Swell Index Test Results.....	7
Table 4.	General Definition of Site Classes	8
Table 5.	Recommended Site Classifications	9

List of Attached Figures

Figure 1 -	Indicative Site Location.....	2
Figure 2 -	Geological Map (Pwj - Jerrys Plains Subgroup).....	3
Figure 3 -	ASS Map Excerpt.....	4

List of Appendices

Appendix A	Development Plans
Appendix B	Photolog
Appendix C	Geotechnical Investigation Locations
Appendix D	Borehole Logs
Appendix E	Laboratory Test Results
Appendix F	Foundation Maintenance and Footing Performance

1 Introduction

EP Risk Management Pty Ltd (EP Risk) was engaged by McCloy Group Pty Ltd to undertake a Site Classification Assessment at Ibis Place, Kurrajong Estate Stage 6, Scone NSW 2337.

The engagement was carried out in line with the conditions of engagement and the investigation scope as outlined in our proposal EP18944 dated 3 March 2025.

The client provided the civil drawings of Kurrajong Estate – Stage 6 by MM Hyndes Bailey included in **Appendix A – Development Plans**.

1.1 Objectives and Scope

It is understood that the site classification is needed following the completion of the earthworks for the twenty-one (21) lots in Stage 6, at Kurrajong Estate, Scone NSW.

EP Risk carried out the following scope of works for the geotechnical investigation:

- Prepared all the work health and safety documentation and procured Before You Dig Australia plans for the site.
- Advanced twenty-one (21) boreholes (BHs) to a maximum depth of 3.0m below ground level (BGL) or prior bedrock refusal.
- Conducted Dynamic Cone Penetrometer (DCP) testing adjacent to the BH to assess the consistency of the subsurface.
- Collection of representative undisturbed samples for laboratory testing.
- Upon completion, the boreholes were filled with spoil and lightly compacted at the surface.
- Preparation of a geotechnical report including investigation findings, laboratory test results, and site classification.

2 Site Location and Description

The Site is located at Ibis Place, Kurrajong Estate, Scone NSW 2337, legally identified as lot 517 DP1294333 and is bounded by Scone Airport to the north, rural land to the west and residential areas to the east and south.

Site elevation is approximately Reduced Level (R.L) 230m Australian Height Datum (AHD) on the southwest corner of the site to approximately R.L 220m AHD on the northeast corner of the site. Site drainage is assumed to follow surface gradient contours in a predominately northeast direction towards lower elevated parts of the site.

Site vegetation comprised of short maintained grass and taller grass primarily on the west and north boundary of the site. Photos collected during site investigation is shown in **Appendix B – Photolog**.

An excerpt from NearMap with the indicative site location is shown in Figure 1.



Figure 1 - Indicative Site Location

3 Desktop Study

3.1 Regional Geology

Based on geological data sourced from NSW Government website (www.minview.geoscience.nsw.gov.au), the Site is underlain by:

- Lopingian Aged (259.1 – 251.902 Ma) – Jerrys Plains Subgroup (Pwj) of Whittingham Coal Measures known to contain coarse grained sandstone, fine to medium grained lithic to quartz-lithic sandstone, mudstone, coal seams and thin coaly partings, carbonaceous claystone, tuffaceous claystone and siltstone with fossil plant debris, pebbles paraconglomerate.

An excerpt of the geological map is shown in Figure 2.



Figure 2 - Geological Map (Pwj - Jerrys Plains Subgroup)

3.2 Soil Landscape

Based on the information provided by the NSW Office of Environment and Heritage, Soil Landscapes of Central and Eastern NSW, on site soil landscape has been identified as Dartbrook (SI5601db).

Dartbrook soil covers smooth undulating rises and low hills with elevation ranges of 100-140m and 200-260m. Slopes are gently (0-10%) and long and smooth (100-2,500m). Local relief is 30-80m. Drainage lines occur at intervals of 400-600m, with some to 1,000m. Some of this landscape is made up of old gravel terrace remnants by the Hunter River. Minor to moderate sheet erosion on some hillslopes and high shrink-swell potential.

3.3 Mine Subsidence

Reference to the Mine Subsidence District Data Source, the Site is not located within a Mine Subsidence District. Muswellbrook Mine Subsidence District is located 9.5km south from the site.

3.4 Acid Sulphate Soils (ASS)

The NSW Government data available on NSW Planning Portal indicates the site is located in an area with no known acid sulphate soils. An extract of the acid soil sulphate map is shown in Figure 3.




Figure 3 - ASS Map Excerpt

4 Geotechnical Investigation

4.1 Investigation Methodology

The site investigation was conducted on 14 March 2025 under full time supervision of an experienced EP Risk Geotechnical Professional in accordance with AS1726-2017 Geotechnical Site Investigations. The investigation involved the following:

- Preparation of a Safe Work Method Statement (SWMS) for all the fieldwork and procuring the site service plans from Before You Dig Australia.
- Drilling twenty-one (21) boreholes at locations of interest within the footprint of the proposed development.
- Logging of soil/rocks encountered and collection of representative soil and rock samples to be tested by a NATA-accredited laboratory.

The BH were drilled use a 4WD mounted drilling rig fitted with a 100mm V-bit auger. The locations of the BH are shown in **Appendix C – Geotechnical Investigation Locations**.

4.2 Subsurface Profile

A project geological classification has been developed based on the results of the investigation and a summary of the units and their distribution are presented in Table 1 and Table 2. The borehole logs and accompanying explanatory notes are presented in **Appendix D – Borehole Logs**.

Table 1. Observed Geotechnical Units

Unit #	Origin	Material	Description
Unit 1	Topsoil	Silty CLAY	Low to medium plasticity, black
Unit 2	Residual Soil	Silty/Sandy CLAY	Medium to high plasticity, black, brown, white, grey, with fine to medium grained sand, fine to medium grained, sub-rounded to sub-angular gravel.

Table 2. Distribution of Subsurface Geological units Across the Investigated Locations

BH ID	Depth Below Ground Level (m BGL)	
	Topsoil	Residual Soil
	Unit 1	Unit 2
BH01	0.0-0.2	0.2-3.0*
BH02	0.0-0.2	0.2-3.0*
BH03	0.0-0.1	0.1-3.0*
BH04	0.0-0.1	0.1-3.0*
BH05	0.0-0.2	0.2-3.0*
BH06	0.0-0.2	0.2-3.0*
BH07	0.0-0.2	0.2-3.0*
BH08	0.0-0.2	0.2-3.0*
BH09	0.0-0.2	0.2-3.0*
BH10	0.0-0.2	0.2-3.0*
BH11	0.0-0.2	0.2-3.0*
BH12	0.0-0.2	0.2-3.0*
BH13	0.0-0.2	0.2-3.0*
BH14	0.0-0.1	0.1-3.0*
BH15	0.0-0.1	0.1-3.0*
BH16	0.0-0.1	0.1-3.0*
BH17	0.0-0.1	0.1-3.0*
BH18	0.0-0.1	0.1-3.0*
BH19	0.0-0.1	0.1-3.0*
BH20	0.0-0.1	0.1-3.0*
BH21	0.0-0.2	0.2-3.0*
*)-limit of the investigation NE-not encountered		

4.3 Groundwater

Groundwater was not encountered during the investigation. It should be noted that groundwater conditions will vary with seasonal changes and weather conditions along with site related conditions.

4.4 Laboratory Results

Geotechnical laboratory testing was conducted on selected bulk, disturbed and undisturbed samples collected during the site investigation. All testing was performed by Coffey Testing – NATA accredited laboratory in accordance with the relevant Australian Standards and technical procedures. The detailed results of laboratory testing are presented in **Appendix E – Laboratory Test Results** and are summarised in the following sections.

4.4.1 Shrink Swell

Undisturbed soil samples were collected during the site investigation and the shrink-swell test results are presented in Table 3.

Table 3. Shrink-Swell Index Test Results								
BH ID	Soil Type	Depth (m BGL)	Shrinkage		Swell			Shrink – Swell Index (Iss%)
			Shrinkage Field Moisture Content (%)	Dried Shrinkage (%)	Field Moisture Content (%)	Inundated Moisture Content (%)	Swell Strain (%)	
BH03	Silty CLAY	0.6-1.1	28.8	6.0	27.2	40.5	7.1	5.3
BH06	Silty CLAY	0.5-1.0	30.7	7.6	33.7	40.8	5.2	5.7
BH09	Silty CLAY	0.5-1.0	26.8	5.5	28.7	38.9	7.9	5.2
BH12	Silty CLAY	1.0-1.5	24.7	6.4	26.6	35.9	8.2	5.8
BH13	Silty CLAY	0.6-1.1	28.2	6.6	28.3	35.9	5.7	5.3
BH16	Silty CLAY	0.6-1.1	31.2	6.9	30.0	37.5	8.9	6.3
BH19	Silty CLAY	0.6-1.1	31.9	6.6	30.8	39.6	6.0	5.3
Lot 607	Silty CLAY	0.7-1.0	28.4	5.1	28.9	31.1	6.3	4.6

5 Preliminary Site Classification

Australian Standard AS 2870-2011 establishes performance requirements and specific designs for common foundation conditions as well as providing guidance on the design of footing systems using engineering principles. Site classes as defined on Table 2.1 and 2.3 of AS 2870 are presented in Table 4.

Site Class	Foundation	Characteristic Surface Movement
A	Most sand and rock sites with little or no ground movement from moisture changes	-
S	Slightly reactive clay sites, which may experience only slight ground movement from moisture changes	0 – 20 mm
M	Moderately reactive clay or silt sites, which may experience moderate ground movement from moisture changes	20 – 40 mm
H1	Highly reactive clay sites, which may experience high ground movement from moisture changes	40 – 60 mm
H2	Highly reactive clay sites, which may experience very high ground movement from moisture changes	60 – 75 mm
E	Extremely reactive sites, which may experience extreme ground movement from moisture changes	> 75 mm
A to P	Filled sites (refer to clause 2.4.6 of AS 2870)	-
P	Sites which include soft soils, such as soft clay or silt or loose sands; landslip; mine subsidence; collapsing soils; soils subject to erosion; reactive sites subject to abnormal moisture conditions or sites which cannot be classified otherwise.	

Reactive sites are sites consisting of clay soils that swell on wetting and shrink on drying, resulting in ground movements that can damage lightly loaded structures. The amount of ground movement is related to the physical properties of the clay and environmental factors such as climate, vegetation, and watering. A higher probability of damage can occur on reactive sites where abnormal moisture conditions occur, as defined in AS 2870, due to factors such as:

- Presence of trees on the building site or adjacent site, removal of trees prior to or after construction, and the growth of trees too close to a footing. The proximity of mature trees and their effect on foundations should be considered when determining building areas within each allotment (refer to AS 2870).
- Failure to provide adequate site drainage or lack of maintenance of site drainage, failure to repair plumbing leaks and excessive or irregular watering of gardens.
- Unusual moisture conditions caused by removal of structures, ground covers (such as pavements), drains, dams, swimming pools, tanks etc.

Regarding the performance of footings systems, AS 2870 states “footing systems designed and constructed in accordance with this Standard on a normal site (see Clause 1.3.2) that is:

- a) not subject to abnormal moisture conditions; and
- b) maintained, such that the original site classification remains valid and abnormal moisture conditions do not develop, are expected to usually experience no damage, a low incidence of damage category 1 and an occasional incidence of damage category 2.”

Damage categories are defined in Appendix C of AS 2870, which is reproduced in CSIRO Information Sheet BTF 18, Foundation Maintenance and Footing Performance: A Homeowner’s Guide attached as **Appendix F – Foundation Maintenance and Footing Performance**.

The laboratory test results summarised in Table 3 indicate that the tested natural clay soils are highly reactive with I_{ss} values ranging from 5.2% to 6.3%.

The classification of sites with controlled fill of depths greater than 0.4m (deep fill) comprising of material other than sand would be Class P. An alternative classification may however be given to sites with controlled fill where consideration is made to the potential for movement of the fill and underlying soil based on the moisture conditions at the time of construction and the long-term equilibrium moisture conditions.

Based on the subsurface profiles encountered during the test bores and in accordance with AS2870-2011; the site in its existing condition and in the absence of abnormal moisture conditions received a site classification of **Class E Extremely Reactive**, based on characteristics surface movement alone.

Following review of borehole logs and laboratory test results, EP Risk recommended Site Classification for footing and slab design as detailed in Table 5.

Table 5. Recommended Site Classifications	
Lots	Recommended Site Classification
1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21	Class E-D, Extremely Reactive

The above site classification assume that all foundations are founded below any topsoil, uncontrolled fill or slope wash and on natural soil profile or engineered fill. Characteristic surface movement of approximately 107mm to 130mm have been calculated for the lots in its existing condition at the time of investigation. Where the cracked zone has been eliminated due to regrade activities, the characteristic surface movement could be in excess of 140mm in the worst-case scenario. Due to the highly reactive soils to >3.0m depth across the lot, **Class E**, is recommended for footing and slab design.

The above site classification and footings recommendations are for the site conditions present at the time of fieldwork and consequently the site classifications may need to be reviewed with consideration of any site works that may be undertaken after the investigation and this report. Site works may include:

- Changes to the existing soil profile by cutting and filling.
- Landscaping, including trees removed or planted in the general building area; and
- Drainage and watering systems.

Designs and design methods presented in AS 2870-2011 are based on the performance requirement that significant damage can be avoided if site conditions are properly maintained. Performance requirements and foundation maintenance are outlined in Appendix B of AS 2870. The above site classification assumes that the performance requirements as set out in Appendix B of AS 2870 are acceptable and that site foundation maintenance is undertaken to avoid extremes of wetting and drying.

Details on appropriate site and foundation maintenance practices are presented in Appendix B of AS 2870-2011 and in CSIRO Information Sheet BTF 18, Foundation Maintenance and Footing Performance: A Homeowner's Guide. Adherence to the detailing requirement outlined in Section 5 of AS 2870-2011 is essential, Section 5.6. Additional requirements for Classes M, H1, H2 and E sites, including architectural restrictions, plumbing and drainage requirements.

5.1 Footings

All foundations should be designed and constructed in accordance with AS 2870-2011, Residential Slabs and Footings, with reference to site classifications as presented in Table 5.

All footings should be founded below any deleterious soils or uncontrolled fill in stiff or better residual clay. All footings for the same structure should be founded on strata of similar stiffness and reactivity to minimise the risk of differential movements.

Piered footings for residential type light weight structures do not necessarily need to be founded in the natural soils where fill is undertaken in accordance with AS3798-2007.

Due to the reactivity of the site soils being E-D, extremely reactive it is likely that piercing will be required unless the slab and foundations are specifically designed to accommodate the potential volume change in the subsurface profile.

5.1.1 High Level Footings

High-level footing alternatives could be expected to comprise slabs on ground with edge beams or pad footings for the support of concentrated loads. Such footings designed in accordance with engineering principles and founded in stiff or better natural soils (residual soils) or in controlled fill (placed and compacted in accordance with AS3798-2007) may be proportioned on an allowable bearing capacity of 100kPa for controlled fill or for stiff or better residual clay. The founding conditions should be assessed by a geotechnical consultant or experienced engineer to confirm suitable conditions.

5.1.2 Piered Footings

Piered footings are considered as an alternative to deep edge beams or high-level footings. It is suggested that piered footings, founded in stiff or better clay soils or controlled fill could be proportioned on an end bearing pressure of 150kPa. It would be anticipated that piercing will be required to address the reactivity of the site being Class E-D, unless the footings and slab are designed and constructed to accommodate the potential volume change associated with variance in the soil moisture profile due to seasonal and climatic conditions.

Where piered footings are utilised, the potential for volume change in the subsurface profile should be taken into consideration by the designer, along with potential settlement when founded in controlled fill.

All footings should be founded below any topsoil, slopewash, deleterious soils or uncontrolled fill. All footings for the same structure should be founded on strata of similar stiffness and reactivity to minimise the risk of differential movements.

Inspection of high level or pier footings excavations should be undertaken to confirm the founding conditions, and the base should be cleared of fall-in prior to the formation of the footing.

6 References

- Austroads AGPT02-17, "Guide to Pavement Technology Part 2: Pavement Structural Design," Austroads Ltd, 2017.
- eSPADE, Online website of NSW Office of Environment and heritage (www.environment.nsw.gov.au)
- Look, Burt – Handbook of Geotechnical Investigation and Design Tables, Taylor & Francis 2007.
- NearMap, [MapBrowser](#) | [Nearmap](#)
- Minview, ([MinView](#) | [Regional NSW](#) | [Mining, Exploration and Geoscience](#))
- NSW Department of Planning and Environment, Resources and Geoscience (www.resourcesandgeoscience.nsw.gov.au)
- Safe Work Australia, Excavation Work Code of Practice, January 2020
- Standards Australia, AS1726-2017, "Geotechnical site investigations".
- Standards Australia AS2870-2011, "Residential Slabs and Footings".
- Standards Australia AS3798-2007, "Guidelines on Earthworks for Commercial and Residential Structures".
- Standards Australia, HB 160 – Soils Testing, 2006

Appendix A

DEVELOPMENT PLANS

KURRAJONG ESTATE - STAGE 6

DA162/99



DESIGN FOR ROAD, DRAINAGE, SEWER & WATER RETICULATION WORKS

CLIENT: MCCLOY GROUP

SHEET INDEX


COVER_001	COVER AND SHEET INDEX
CIVIL_001	OVERALL GENERAL ARRANGEMENT
CIVIL_002	GENERAL ARRANGEMENT CH345 TO CH570
CIVIL_003	GENERAL ARRANGEMENT CH555 TO END OF WORKS
CIVIL_004	LONGITUDINAL SECTION
CIVIL_005	CROSS SECTIONS CH356.74-CH361.68 & TYPICAL SECTION
CIVIL_006	CROSS SECTIONS CH375 TO CH417.97
CIVIL_007	CROSS SECTIONS CH420 TO CH465
CIVIL_008	CROSS SECTIONS CH480 TO CH525
CIVIL_009	CROSS SECTIONS CH480 TO CH525
CIVIL_010	CROSS SECTIONS CH608.7 TO CUL-DE-SAC HEAD
CIVIL_011	KERB RETURN - 1
SEW_001	SEWER & WATER - GENERAL ARRANGEMENT
SEW_002	SEWER LONGITUDINAL SECTION- SEWER LINE A
SEW_003	SEWER LONGITUDINAL SECTION- SEWER LINE B
SEW_004	SEWER TYPICAL DETAILS
SEW_005	SEWER TYPICAL DETAILS
SEW_006	SEWER TYPICAL DETAILS
SEW_007	SEWER TYPICAL DETAILS
SED_001	SEDIMENT AND EROSION CONTROL PLAN
DRAIN_001	STORM WATER LONGITUDINAL SECTION
DRAIN_002	STORMWATER - CROSS SECTION CH15 TO CH162.62
DRAIN_003	DRAINAGE LONG SECTIONS- LINE 1
DRAIN_004	DRAINAGE LONG SECTIONS- LINE 2, 3, 4 & 5
DRAIN_005	DRAINAGE LONG SECTIONS- LINE 6 & 7
DRAIN_006	RAINFALL DATA AND CATCHMENT PLAN
DRAIN_007	DRAINS DATA
DRAIN_008	DRAINS RESULTS 20% AEP
DRAIN_009	DRAINS RESULTS 1% AEP


UPPER HUNTER SHIRE COUNCIL

This document forms part of the approval referred to in Council's notice of Determination


Dated 27 April 2023

No SWC 162/1999


Endorsed by  For General Manager



Version No.	Details	
A	ORIGINAL ISSUE	OCTOBER 2022
B	STORMWATER UPDATE	JANUARY 2023
C	INTER ALLOTMENT UPDATE	MARCH 2023





- 1 These drawings are to be read in conjunction with the Earthworks and Pavement specification and the Upper Hunter Shire Council Guidelines for Subdivision and Developments.
- 2 The drawings are a diagrammatic representation of the work only and dimensions shall not be scaled.
- 3 Dimensions of all Lots are subject to final survey.
- 4 Erosion and sedimentation controls are to be placed prior to earthworks commencing in accordance with the drawings and specifications.
 - a. Controls are to be in checked daily and cleared after storm events;
 - b. Controls shall be in place at the end of each day;
 - c. Disturbed areas shall be topsoiled and grassed as soon as practicable.
- 5 It is the responsibility of any persons/contractors using this plan to locate and expose all underground services prior to the commencement of their work and to make their own separate enquiries with, DIAL BEFORE YOU DIG.
- 6 All disturbed areas shall be reinstated with a minimum of 100 mm of topsoil and grass seeded.
- 7 Hours of work are to be confined to the hours specified by Upper Hunter Shire Council.
- 8 Disturbance of the site and surrounding areas are to be kept to a minimum and access to local properties maintained at all times.
- 9 Make smooth transition to existing road and surfaces.
- 10 Cleanouts for subsoil to be provided at high points and every 60m.
- 11 Roof water connections to be placed in K26 in location directed by Superintendent








PLANS PREPARED BY		CLIENT		GENERAL ARRANGEMENT PLAN - CH345 TO CH570 STAGE 6 KURRAJONG ESTATE, SATUR		SCALE: 1:500 ORIGINAL DRAWING SIZE: A1		PLAN ISSUE		07.03.2023
MM HYNDES BAILEY & Co. REGISTERED SURVEYORS - TOWN PLANNING - CIVIL DESIGN <i>Surveying the Hunter since 1920</i>  Email: office@hbsurveys.com.au (PO Box 26), MUSWELLBROOK NSW 2333				DESIGN: M. COLE R. JONES		DRAWN: M. COLE R. JONES		A	ISSUE TO COUNCIL	REV: C
						LGA: UPPER HUNTER		B	STORMWATER UPDATE	
						FILE:207203_S6_ENG		C	INTER ALLOTMENT UPDATE	JOB REF: 207203
						SHEET: CIVIL_002				







PLANS PREPARED BY		CLIENT		GENERAL ARRANGEMENT PLAN - CH 555 TO END OF WORKS STAGE 6 KURRAJONG ESTATE, SATUR		SCALE: 1:500 ORIGINAL DRAWING SIZE: A1		PLAN ISSUE		07.03.2023
MM HYNDES BAILEY & Co. REGISTERED SURVEYORS - TOWN PLANNING - CIVIL DESIGN <i>Surveying the Hunter since 1920</i> Email: office@hbsurveys.com.au (PO Box 26), MUSWELLBROOK NSW 2333				DESIGN: M. COLE R. JONES		DRAWN: M. COLE R. JONES		A	ISSUE TO COUNCIL	REV: C
						LGA: UPPER HUNTER		B	STORMWATER UPDATE	
						FILE:207203_S6_ENG SHEET: CIVIL_003		C	INTER ALLOTMENT UPDATE	JOB REF: 207203



- PAVEMENT DETAILS
- PAVEMENT DESIGN BASED ON HUNTER GEOTECHNICS
DATED JAN 2008
1. 150mm 3% LIME STABILISED SUBGRADE
 2. 270mm SUBBASE COURSE (UNBOUND)
 3. 180mm BASE COURSE (UNBOUND)
 4. 14mm/7mm 2 COAT SEAL




PLANS PREPARED BY		CLIENT		IBIS PLACE LONGITUDINAL SECTION & DETAILS STAGE 6 KURRAJONG ESTATE, SATUR		SCALE: AS SHOWN ORIGINAL DRAWING SIZE: A1 LGA: UPPER HUNTER		PLAN ISSUE		07.03.2023
MM HYNDES BAILEY & Co. REGISTERED SURVEYORS - TOWN PLANNING - CIVIL DESIGN Surveying the Hunter since 1920 Ph: 02 65432475 Email: office@hbsurveys.com.au (PO Box 26), MUSWELLBROOK NSW 2333				DESIGN: M. COLE R. JONES		DRAWN: M. COLE R. JONES		A	ISSUE TO COUNCIL	REV: C
						FILE:207203_S6_ENG		B	STORMWATER UPDATE	
						SHEET: CIVIL_004		C	INTER ALLOTMENT UPDATE	JOB REF: 207203




TYPICAL CROSS SECTION
IBIS PLACE
CH 356.74 - 584.53


PLANS PREPARED BY		CLIENT		CROSS SECTIONS CH 356.74 - 361.68 & TYPICAL SECTION STAGE 6 KURRAJONG ESTATE, SATUR		SCALE: 1:1000 ORIGINAL DRAWING SIZE: A1 LGA: UPPER HUNTER FILE:207203_S6_ENG SHEET: CIVIL_005		PLAN ISSUE		07.03.2023
MM HYNDES BAILEY & Co. REGISTERED SURVEYORS - TOWN PLANNING - CIVIL DESIGN Surveying the Hunter since 1920 Ph: 02 65432475 Email: office@hbsurveys.com.au (PO Box 26), MUSWELLBROOK NSW 2333				DESIGN:		DRAWN:		A	ISSUE TO COUNCIL	REV: C
				M. COLE R. JONES		M. COLE R. JONES		B	STORMWATER UPDATE	
								C	INTER ALLOTMENT UPDATE	JOB REF: 207203




PLANS PREPARED BY		CLIENT		CROSS SECTIONS CH 375 - 417.97 STAGE 6 KURRAJONG ESTATE, SATUR		SCALE: 1:1000		PLAN ISSUE		07.03.2023
MM HYNDES BAILEY & Co. REGISTERED SURVEYORS - TOWN PLANNING - CIVIL DESIGN Surveying the Hunter since 1920 Ph: 02 65432475 Email: office@hbsurveys.com.au (PO Box 26), MUSWELLBROOK NSW 2333 						ORIGINAL DRAWING SIZE: A1		A	ISSUE TO COUNCIL	REV: C
						LGA: UPPER HUNTER		B	STORMWATER UPDATE	
		DESIGN: M. COLE R. JONES		DRAWN: M. COLE R. JONES		FILE:207203_S6_ENG		C	INTER ALLOTMENT UPDATE	JOB REF: 207203
						SHEET: CIVIL_006				




465



450




435




420


PLANS PREPARED BY		CLIENT		CROSS SECTIONS CH 420 - 465 STAGE 6 KURRAJONG ESTATE, SATUR		SCALE: 1:1000 ORIGINAL DRAWING SIZE: A1		PLAN ISSUE		07.03.2023
MM HYNDES BAILEY & Co. REGISTERED SURVEYORS - TOWN PLANNING - CIVIL DESIGN Surveying the Hunter since 1920 Ph: 02 65432475 Email: office@hbsurveys.com.au (PO Box 26), MUSWELLBROOK NSW 2333				DESIGN: M. COLE R. JONES		LGA: UPPER HUNTER		A	ISSUE TO COUNCIL	REV: C
				DRAWN: M. COLE R. JONES		FILE:207203_S6_ENG		B	STORMWATER UPDATE	
						SHEET: CIVIL_007		C	INTER ALLOTMENT UPDATE	JOB REF: 207203




525



510




495




480


PLANS PREPARED BY		CLIENT		CROSS SECTIONS CH 480 - 525		SCALE: 1:100		PLAN ISSUE		07.03.2023			
MM HYNDES BAILEY & Co. REGISTERED SURVEYORS - TOWN PLANNING - CIVIL DESIGN Surveying the Hunter since 1920 Ph: 02 65432475 Email: office@hbsurveys.com.au (PO Box 26), MUSWELLBROOK NSW 2333 				STAGE 6		ORIGINAL DRAWING SIZE: A1		A	ISSUE TO COUNCIL		REV: C		
				KURRAJONG ESTATE, SATUR		LGA: UPPER HUNTER		B	STORMWATER UPDATE				
				DESIGN:		DRAWN:		FILE:207203_S6_ENG		C	INTER ALLOTMENT UPDATE		JOB REF: 207203
				M. COLE R. JONES		M. COLE R. JONES		SHEET: CIVIL_008					




584.53



570





555





540

PLANS PREPARED BY		CLIENT		CROSS SECTIONS CH 480 - 525		SCALE: 1:100		PLAN ISSUE		07.03.2023
MM HYNDES BAILEY & Co. REGISTERED SURVEYORS - TOWN PLANNING - CIVIL DESIGN Surveying the Hunter since 1920 Ph: 02 65432475 Email: office@hbsurveys.com.au (PO Box 26), MUSWELLBROOK NSW 2333				STAGE 6		ORIGINAL DRAWING SIZE: A1		A	ISSUE TO COUNCIL	REV: C
				KURRAJONG ESTATE, SATUR		LGA: UPPER HUNTER		B	STORMWATER UPDATE	
				DESIGN:	DRAWN:	FILE:207203_S6_ENG		C	INTER ALLOTMENT UPDATE	JOB REF: 207203
				M. COLE R. JONES	M. COLE R. JONES	SHEET: CIVIL_009				



KERB RETURN - 1
H=1:200





WATER SERVICES

20mm COPPER SERVICE COIL STANDARD SPLIWIWI
PROVIDE 2 20mm SERVICES
ROAD CROSSING 20mm COPPER SERVICE 100mm DW PIP S6

H DRAINAGE
MANHOLE SPACING 120m

SOP CALLO SOWER MAIN


WATER MAINS POLYETHYLENE GLASS REINFORCED PIPE
PRESSURE PIPE FOR WATER SUPPLY P12 IN ACCORDANCE
WITH WSA PS 209
PIPE SIZE 100mm DIAMETER UNLESS OTHERWISE SPECIFIED PLAIN

ALL PIPES SHALL BE COILED IRON WITH COPE
DRAINS WHICH WILL BE SOILESS SPOOL SPRING DRAINS
IN ACCORDANCE WITH ASSPEC C401


SEWER SERVICES

RAIN MAINS POLYETHYLENE GLASS REINFORCED PIPE
CLASS S


PLANS PREPARED BY		CLIENT		SEWER & WATER RETICULATION - GENERAL ARRANGEMENT		SCAL 1:1000		PLANNING ISS		07/03/2023
MM HYNDES BAILEY & Co. REGISTERED SURVEYORS - TOWN PLANNING - CIVIL DESIGN Surveying the Hunter since 1920 PROJECT: 643247 DATE: 26/01/2023 SW: 2333		McCLOY GROUP		STAGE 6		RISE & FALL DRAWING SCALE A1		A	ISSUE 001	
				KURRAJONG ESTATE, SATUR		LGA: UPPER HUNTER			SOURMWAOR PDA	RCC
				DESIGN:	DRAWN:	FILE: 207203_S6_SEW		C	ISSUE ALL M PDA	
				M. COLE R. JONES	M. COLE R. JONES	SHEET: SEW_001				207203




SEWER LINE A




SEWER LINE A






ADDITIONAL INFORMATION PROVIDED IN SEW-1100 SERIES COMMENTARY




ADDITIONAL INFORMATION PROVIDED IN SEW-1100 SERIES COMMENTARY




ADDITIONAL INFORMATION PROVIDED IN SEW-1100 SERIES COMMENTARY


PLANS PREPARED BY		CLIENT		SEWAGE DETAILS IN ACCORDANCE WITH		SCAL ⁰⁰ AS S ⁰⁰ W ⁰⁰		PLA ⁰⁰ ISS ⁰⁰		07/03/2023	
MM HYNDES BAILEY & Co. REGISTERED SURVEYORS - TOWN PLANNING - CIVIL DESIGN Surveying the Hunter since 1920 P⁰⁰02 6 43247⁰⁰ all⁰⁰ 000000000000000000⁰⁰ 000											




ADDITIONAL INFORMATION PROVIDED IN SEW-1300 SERIES COMMENTARY



ADDITIONAL INFORMATION PROVIDED IN SEW-1300 SERIES COMMENTARY




ADDITIONAL INFORMATION PROVIDED IN SEW-1300 SERIES COMMENTARY




ADDITIONAL INFORMATION PROVIDED IN SEW-1300 SERIES COMMENTARY


PLANS PREPARED BY		CLIENT		SEWAGE DETAILS IN ACCORDANCE WITH		SCAL ⁰⁰ AS S ⁰⁰ W ⁰⁰		PLA ⁰⁰ ISS ⁰⁰		07/03/2023	
MM HYNDES BAILEY & Co. REGISTERED SURVEYORS - TOWN PLANNING - CIVIL DESIGN Surveying the Hunter since 1920 P:02 643247											



ADDITIONAL INFORMATION PROVIDED IN SEW-1300 SERIES COMMENTARY





ADDITIONAL INFORMATION PROVIDED IN SEW-1300 SERIES COMMENTARY

PLANS PREPARED BY MM HYNDES BAILEY & Co. REGISTERED SURVEYORS - TOWN PLANNING - CIVIL DESIGN <i>Surveying the Hunter since 1920</i>  P:02 6432470 F:02 6432471 IP:02 6432470 M:SWILLERS SW 2333	CLIENT 	SEWAGE DETAILS IN ACCORDANCE WITH SEWAGE CODE OF AUSTRALIA WATER SERVICES ASSOCIATION OF AUSTRALIA DESIGN: M. COLE R. JONES DRAWN: M. COLE R. JONES	SCAL: AS SHOWN RIGID DRAWING SCALE LGA: UPPER HUNTER FILE:207203_S6_SEW SHEET: SEW_007	PLA: ISS	07/03/2023
				A: ISS CIL	R: C
				S: RMWA: R PDA	
				C: I: R ALL: M: PDA	
					207203


EROSION & SEDIMENTATION CONTROL NOTES

1. All works to be carried out in accordance with UPPER HUNTER SHIRE COUNCIL Engineering Guidelines for Subdivisions and Developments.
2. Erosion and sedimentation control devices are to be installed as required prior to site disturbance.
3. Site disturbance and vegetation removal shall be kept to the absolute minimum.
4. Silt is to be cleared from devices after all storm events.
5. All control devices are to be checked and maintained on a regular basis and adjustments made as necessary to ensure effective on going control.
6. All control devices are to be in place at the end of each days work.
7. Earthworks shall be rolled at the end of each day for stabilisation.
8. Topsoil shall be removed, stockpiled and stabilised for later re-use.
9. Excavated soil is to be mounded on the up hillside of trenches wherever possible.
10. Denuded areas are to be topsoiled and seeded as soon as practicable.
11. Provide turf strip behind kerb and gutter. Turf to be placed as soon as concrete kerbing has set.




KERB INLET PIT SEDIMENT TRAP DETAIL - ST

N.T.S.
IN ACCORDANCE WITH LANDCOM 'BLUE BOOK'
S06-11 MESH AND GRAVEL INLET FILTER





SANDBAG KERB INLET SEDIMENT TRAP DETAIL - SB

N.T.S.



MULCH AND GRASS SEED ANY
DISTURBED AREAS




Construction Notes

1. Construct the straw bale filter as close as possible to being parallel to the contours of the site.
2. Place bales lengthwise in a row with ends tightly abutting. Use straw to fill any gaps between bales. Straws are to be placed parallel to ground.
3. Ensure that the maximum height of the filter is one bale.
4. Embed each bale in the ground 75 mm to 100 mm and anchor with two 1.2 metre star pickets or stakes. Angle the first star picket or stake in each bale towards the previously laid bale. Drive them 600 mm into the ground and, if possible, flush with the top of the bales. Where star pickets are used and they protrude above the bales, ensure they are fitted with safety caps.
5. Where a straw bale filter is constructed downslope from a disturbed batter, ensure the bales are placed 1 to 2 metres downslope from the toe.
6. Establish a maintenance program that ensures the integrity of the bales is retained - they could require replacement each two to four months.

STRAW BALE FILTER

SD 6-7



Construction Notes

1. Strip the topsoil, level the site and compact the subgrade.
2. Cover the area with needle-punched geotextile.
3. Construct a 200-mm thick pad over the geotextile using road base or 30-mm aggregate.
4. Ensure the structure is at least 15 metres long or to building alignment and at least 3 metres wide.
5. Where a sediment fence joins onto the stabilised access, construct a hump in the stabilised access to divert water to the sediment fence.

STABILISED SITE ACCESS

SD 6-14

Construction Notes

1. Construct sediment fences as close as possible to being parallel to the contours of the site, but with small returns as shown in the drawing to limit the catchment area of any one section. The catchment area should be small enough to limit water flow if concentrated at one point to 50 litres per second in the design storm event, usually the 10-year event.
2. Cut a 150-mm deep trench along the upslope line of the fence for the bottom of the fabric to be entrenched.
3. Drive 1.5 metre long star pickets into ground at 2.5 metre intervals (max) at the downslope edge of the trench. Ensure any star pickets are fitted with safety caps.
4. Fix self-supporting geotextile to the upslope side of the posts ensuring it goes to the base of the trench. Fix the geotextile with wire ties or as recommended by the manufacturer. Only use geotextile specifically produced for sediment fencing. The use of shade cloth for this purpose is not satisfactory.
5. Join sections of fabric at a support post with a 150-mm overlap.
6. Backfill the trench over the base of the fabric and compact it thoroughly over the geotextile.

SEDIMENT FENCE

SD 6-8

PLANS PREPARED BY

MM HYNDES BAILEY & Co.
REGISTERED SURVEYORS - TOWN PLANNING - CIVIL DESIGN
Surveying the Hunter since 1920



P:02 6743247
P:02 6743247
P:02 6743247

CLIENT



SEDIMENT & EROSION CONTROL PLAN
STAGE 6
KURRAJONG ESTATE, SATUR

DESIGN:
M. COLE
R. JONES

DRAWN:
M. COLE
R. JONES

SCALE 1:1000

RI:IAL DRAWI SI:IA1

LGA: UPPER HUNTER

FILE:207203_S6_SED

SHEET: SED_001

PLA ISS

A ISS CIL

S RMWA PDA


C I OR ALL M PDA

07/03/2023

R C


R

207203




STORMWATER OVERFLOW PATH

H=1:500 V=1:100




TYPICAL CROSS SECTION
STORMWATER OVERFLOW PATH
CH 15 - 45




TYPICAL CROSS SECTION
STORMWATER OVERFLOW PATH
CH 62.19 - 162.62


PLANS PREPARED BY		CLIENT		STORMWATER OVERFLOW PATH LONGITUDINAL SECTION & TYPICAL SECTIONS STAGE 6 KURRAJONG ESTATE, SATUR		SCALE: AS SHOWN ORIGINAL DRAWING SIZE: A1		PLAN ISSUE		07.03.2023
MM HYNDES BAILEY & Co. REGISTERED SURVEYORS - TOWN PLANNING - CIVIL DESIGN Surveying the Hunter since 1920 Ph: 02 65432475 Email: office@hbsurveys.com.au (PO Box 26), MUSWELLBROOK NSW 2333				DESIGN:		DRAWN:		A	ISSUE TO COUNCIL	REV: C
				M. COLE R. JONES		M. COLE R. JONES		B	STORMWATER UPDATE	
						FILE:207203_S6_ENG		C	INTER ALLOTMENT UPDATE	JOB REF: 207203
						SHEET: DRAIN_001				




60




45




30




15




105




90




75




61.19




159.45




150



135



120



161.62

PLANS PREPARED BY

MM HYNDES BAILEY & Co.
REGISTERED SURVEYORS - TOWN PLANNING - CIVIL DESIGN
Surveying the Hunter since 1920

Ph: 02 65432475 Email: office@hbsurveys.com.au
(PO Box 26), MUSWELLBROOK NSW 2333



CLIENT



STORMWATER OVERFLOW PATH
CROSS SECTIONS CH 15 - 162.62
STAGE 6
KURRAYONG ESTATE, SATUR

DESIGN:

M. COLE
R. JONES

DRAWN:

M. COLE
R. JONES

SCALE: H 1:100 V 1:100
ORIGINAL DRAWING SIZE: A1
LGA: UPPER HUNTER
FILE:207203_S6_ENG
SHEET: DRAIN_002


PLAN ISSUE

A	ISSUE TO COUNCIL
B	STORMWATER UPDATE
C	INTER ALLOTMENT UPDATE

07.03.2023

REV: C





JOB REF:
207203




LINE 1




PLANS PREPARED BY		CLIENT		DRAINAGE LONG SECTION - LINE 1		SCALE: H 1:100		PLAN ISSUE		07.03.2023
MM HYNDES BAILEY & Co. REGISTERED SURVEYORS - TOWN PLANNING - CIVIL DESIGN <i>Surveying the Hunter since 1920</i> Ph: 02 65432475 Email: office@hbsurveys.com.au (PO Box 26), MUSWELLBROOK NSW 2333		MC McCLOY GROUP		STAGE 6		ORIGINAL DRAWING SIZE: A1		A	ISSUE TO COUNCIL	REV: C
				KURRAJONG ESTATE, SATUR		LGA: UPPER HUNTER		B	STORMWATER UPDATE	
				DESIGN:	DRAWN:	FILE:207203_S6_DRAIN		C	INTER ALLOTMENT UPDATE	JOB REF: 207203
				M. COLE R. JONES	M. COLE R. JONES	SHEET: DRAIN_003				



PLANS PREPARED BY		CLIENT		DRAINAGE LONG SECTIONS - LINE 2, 3 4 & 5		SCALE: H 1:100		PLAN ISSUE		07.03.2023
MM HYNDES BAILEY & Co. REGISTERED SURVEYORS - TOWN PLANNING - CIVIL DESIGN Surveying the Hunter since 1920 Ph: 02 65432475 Email: office@hbsurveys.com.au (PO Box 26), MUSWELLBROOK NSW 2333		McCLOY GROUP		STAGE 6		ORIGINAL DRAWING SIZE: A1		A	ISSUE TO COUNCIL	REV: C
				KURRAJONG ESTATE, SATUR		LGA: UPPER HUNTER		B	STORMWATER UPDATE	
				DESIGN:		DRAWN:		C	INTER ALLOTMENT UPDATE	JOB REF: 207203
				M. COLE R. JONES		M. COLE R. JONES				
						FILE:207203_S6_DRAIN				
						SHEET: DRAIN_004				



LINE 6



LINE 7




PLANS PREPARED BY		CLIENT		DRAINAGE LONG SECTIONS - LINE 6 & 7		SCALE: H 1:100		PLAN ISSUE		07.03.2023
MM HYNDES BAILEY & Co. REGISTERED SURVEYORS - TOWN PLANNING - CIVIL DESIGN Surveying the Hunter since 1920 Ph: 02 65432475 Email: office@hbsurveys.com.au (PO Box 26), MUSWELLBROOK NSW 2333		MC McCLOYGROUP		STAGE 6		ORIGINAL DRAWING SIZE: A1		A	ISSUE TO COUNCIL	REV: C
				KURRAJONG ESTATE, SATUR		LGA: UPPER HUNTER		B	STORMWATER UPDATE	
				DESIGN:	DRAWN:	FILE:207203_S6_DRAIN		C	INTER ALLOTMENT UPDATE	JOB REF: 207203
				M. COLE R. JONES	M. COLE R. JONES	SHEET: DRAIN_005				

DRAINS INPUTS

Australian Rainfall & Runoff Data Hub - Results

Input Data

Longitude	150.833
Latitude	-32.043
Selected Regions (clear)	
River Region	show
ARF Parameters	show
Storm Losses	show
Temporal Patterns	show
Areal Temporal Patterns	show
BOM IFDs	show
Median Preburst Depths and Ratios	show
10% Preburst Depths	show
25% Preburst Depths	show



RAINFALL DATA LOCATION PLAN

IFD DATA ARR 2016

DRAINS MODEL INTIAL LOSS / CONTINUING LOSS (IL/CL)

Initial Loss - Continuing Loss Model

Model NameSCONE STAGE 6

OK

Cancel

Impervious Area Initial Loss (mm)1

Impervious Area Continuing Loss (mm/hr)0

Pervious Area Initial Loss (mm)34

Pervious Area Continuing Loss (mm/hr)0.6

For overland flow use

☐ Friend's equation

☒ Kinematic wave equation

Note: The overland flow equation is only used if you choose to specify more detailed catchment data.

Note: Please click on the Help button above for a detailed description of the IL-CL model.

In summary:

1. DRAINS classifies areas as:

- EIA (Effective Impervious Area),

- PA (Pervious Area)

2. The impervious area losses specified above apply to both EIA and RIA

3. The pervious area losses specified above apply to PA

4. This classification avoids the need to vary the PA Losses for urban and rural areas - simply specify the PA losses as for rural areas.

Storm Losses

Note: Burst Loss = Storm Loss - Preburst


Note: These losses are only for rural use and are **NOT FOR DIRECT USE** in urban areas

Note: As this point is in NSW the advice provided on losses and pre-burst on the [NSW Specific Tab of the ARR Data Hub](#) is to be considered. In NSW losses are derived considering a hierarchy of approaches depending on the available loss information. The continuing storm loss information from the ARR Datahub provided below should only be used where relevant under the loss hierarchy (level 5) and where used is to be multiplied by the factor of 0.4.

ID	1819.0
Storm Initial Losses (mm)	34.0
Storm Continuing Losses (mm/h)	1.5 X 0.4 = 0.6mm

TEMPORAL PATTERNS EAST COAST SOUTH

PIT BLOCKING FACTORS SAG 20%
ON GRADE 10%



PLANS PREPARED BY

MM HYNDES BAILEY & Co.
REGISTERED SURVEYORS - TOWN PLANNING - CIVIL DESIGN
Surveying the Hunter since 1920

Ph: 02 65432475 Email: office@hbsurveys.com.au
(PO Box 26), MUSWELLBROOK NSW 2333



CLIENT



RAINFALL DATA AND CATCHMENT PLAN

STAGE 6
KURRAJONG ESTATE, SATUR

DESIGN:
M. COLE
R. JONES

DRAWN:
M. COLE
R. JONES

SCALE: H 1:1000
ORIGINAL DRAWING SIZE: A1

LGA: UPPER HUNTER

FILE:207203_S6_DRAIN

SHEET: DRAIN_006

PLAN ISSUE

A ISSUE TO COUNCIL
B STORMWATER UPDATE
C INTER ALLOTMENT UPDATE

07.03.2023

REV: C

JOB REF:
207203



PIPE DETAILS																			
Name	From	To	Length (m)	U/S IL (m)	D/S IL (m)	Slope (%)	Type	Dia (mm)	I.D. (mm)	Rough	Pipe Is	No. Pipes	Chg From	At Chg	Chg (m)	RI (m)	Chg (m)	RL (m)	etc (m)
Pipe1-1	Pit 1-1	Pit2-1	7.1	230.641	230.57		1 Concrete, 1	450	450	0.3 New		1	Pit1-1		0				
Pipe2-1	Pit2-1	Pit3-1	64	230.54	228.73	2.83	Concrete, 1	450	450	0.3 New		1	Pit2-1		0				
Pipe3-1	Pit3-1	Pit4-1	74.998	228.7	226.73	2.63	Concrete, 1	450	450	0.3 New		1	Pit3-1		0				
Pipe4-1	Pit4-1	Pit5-1	89.547	226.7	224.33	2.65	Concrete, 1	450	450	0.3 New		1	Pit4-1		0				
Pipe5-1	Pit5-1	Pit 6-1	24.501	224.3	223.53	3.14	Concrete, 1	600	600	0.3 New		1	Pit5-1		0				
PipeXX	Pit 6-1	Pit2-7	3	223.5	223.45	1.67	Concrete, 1	600	600	0.3 New		1	Pit6-1		0				
Pipe 6-1	Pit 6-1	Pit 7-1	63.686	223.5	222.11	2.18	Concrete, 1	675	675	0.3 New		1	Pit6-1		0				
Pit2-7	Pit3-7	Pit3-7	63.686	223.4	222.11	2.03	Concrete, 1	675	675	0.3 New		1	Pit2-7		0				
Pit3-7	Pit4-7	Pit3-7	97.394	222.08	221.5	0.6	Concrete, 1	675	675	0.3 New		1	Pit3-7		0				
Pit4-7	HW9-1a	Pit4-7	15.929	221.47	221.39	0.5	Concrete, 1	675	675	0.3 New		1	Pit4-7		0				
Pipe1-4	Pit2-4	Pit2-4	31.511	228.6	227.73	2.76	uPVC, undi	150	154	0.03 New		1	Pit1-4		0				
Pipe2-4	Pit3-4	Pit2-4	34.012	227.7	226.93	2.26	uPVC, undi	225	242	0.03 New		1	Pit2-4		0				
Pipe3-4	Pit4-4	Pit4-4	18.814	226.9	226.53	1.97	PVC, undi	300	303	0.03 New		1	Pit3-4		0				
Pipe4-4	Pit5-4	Pit5-4	15.82	226.5	226.13	2.34	uPVC, undi	300	303	0.03 New		1	Pit4-4		0				
Pipe5-4	Pit6-4	Pit6-4	34.276	226.1	225.33	2.25	uPVC, undi	300	303	0.03 New		1	Pit5-4		0				
Pipe6-4	Pit7-4	Pit7-4	33.903	225.3	224.53	2.27	uPVC, undi	375	386	0.03 New		1	Pit6-4		0				
Pipe7-4	Pit8-4	Pit8-4	32.139	224.5	222.95	4.82	uPVC, undi	375	386	0.03 New		1	Pit7-4		0				
Pipe8-4	Pit9-4	Pit9-4	19.852	222.909	222.58	1.66	uPVC, undi	375	386	0.03 New		1	Pit8-4		0				
Pipe9-4	Pit9-4	Pit 7-1	21	222.575	222.47	0.5	Concrete, 1	375	375	0.3 New		1	Pit9-4		0				
Pipe 7-1	Pit 8-1	Pit 8-1	97.394	222.084	221.5	0.6	Concrete, 1	675	675	0.3 New		1	Pit 7-1		0				
Pipe 8-1	HW 9-1	Pit 8-1	15.929	221.47	221.39	0.5	Concrete, 1	675	675	0.3 New		1	Pit8-1		0				
PIPE 1-6	Pit 1-6	HW 2-6	90	221.9	221.4	0.56	uPVC, not i	300	303	0.03 New		1	Pit 1-6		0				
Pipe1-7	Pit1-7	Pit2-7	20.5	223.84	223.43	2	Concrete, 1	600	600	0.3 New		1	Pit1-7		0				
Pit2-5	Pit2-5	Pit2-5	36.75	225.165	224.43	2	Concrete, 1	450	450	0.3 New		1	Pit2-5		0				
Pipe1-5	Pit1-5	Pit5-1	7.1	224.401	224.33	1	Concrete, 1	450	450	0.3 New		1	Pit1-5		0				
Pipe2-3	Pit2-3	Pit1-3	26.6	227.362	226.83	2	Concrete, 1	450	450	0.3 New		1	Pit2-3		0				
Pipe1-3	Pit1-3	Pit4-1	7.1	226.801	226.73	1	Concrete, 1	450	450	0.3 New		1	Pit1-3		0				
Pipe2-2	Pit2-2	Pit1-2	30.9	229.448	228.83	2	Concrete, 1	450	450	0.3 New		1	Pit2-2		0				
Pipe1-2	Pit1-2	Pit1-1	7.1	228.801	228.73	1	Concrete, 1	450	450	0.3 New		1	Pit1-2		0				

Pipe	Chg (m)	Bottom Flav (m)	Height of S Chg (m)	Bottom Flav (m)	Height of S Chg (m)	Bottom Flav (m)	Height of S etc (m) etc
------	------------	--------------------	------------------------	--------------------	------------------------	--------------------	----------------------------

CHANNEL DETAILS													
Name	From	To	Type	Length (m)	U/S IL (m)	D/S IL (m)	Slope (%)	Base Width (m)	L.B. Slope (1:2)	R.B. Slope (1:2)	Manning n	Depth (m)	Roofed

OVERFLOW ROUTE DETAILS													id	U/S IL	D/S IL	Length (m)
Name	From	To	Travel Time (min)	Spill Level (m)	Crest Length (m)	Weir Coeff. C	Cross Section	Safe Depth Major (m)	Safe Depth Minor (m)	Safe Depth Stov (sq.m/sec)	Bed Slope	D/S Area Contributing %				
OF1-1	Pit 1-1	Pit2-2	0.2				7.5 m road	0.3	0.15	0.4	3.15	100	52700530	232.04	231.05	31.4
OF2-1	Pit2-1	7.5 m road	0.4				7.5 m road	0.3	0.15	0.4	2.87	0	449	232.04	230.2	64.1
OF3-1	Pit3-1	Pit4-1	0.5				7.5 m road	0.3	0.15	0.4	2.68	0	419	230.2	228.2	90.7
OF4-1	Pit4-1	Pit5-1	0.7				7.5 m road	0.3	0.15	0.4	2.65	0	383	228.2	225.81	74.2
OF5-1	Pit5-1	Pit 6-1	0.2				10 m road	0.3	0.15	0.4	3.27	0	348	225.81	224.975	25.5
OF6-1	Pit 6-1	Pit2-7	0.1				10 m road	0.3	0.15	0.4	1	0	12322495	225	224.97	3
OF6-1	Pit2-7	s1	0.5				kurrajong :	0.3	0.2	0.6	2.52	0	64626206	225.05	223.49	61.9
OF1-4	Pit4-4	Pit2-4	0.2				kurrajong :	0.3	0.2	0.6	2.88	0	317	229.5	228.6	31.3
OF2-4	Pit2-4	Pit3-4	0.3				kurrajong :	0.3	0.2	0.6	2.33	0	315	228.6	227.8	34.3
OF3-4	Pit3-4	Pit4-4	0.2				kurrajong :	0.3	0.2	0.6	2.13	0	298	227.8	227.4	18.8
OF4-4	Pit4-4	Pit5-4	0.1				kurrajong :	0.3	0.2	0.6	2.48	0	287	227.4	227	16.1
OF5-4	Pit5-4	Pit6-4	0.3				kurrajong :	0.3	0.2	0.6	2.36	0	264	227	226.2	33.9
OF6-4	Pit6-4	Pit7-4	0.3				kurrajong :	0.3	0.2	0.6	2.33	0	260	226.2	225.4	34.3
OF7-4	Pit7-4	Pit8-4	0.3				kurrajong :	0.3	0.2	0.6	2.52	0	232	225.4	224.6	31.8
OF8-4	Pit8-4	Pit9-4	0.2				6MSPILL	0.3	0.3	0.4	2.27	0	216	224.6	224.15	19.8
OF97885	Pit9-4	s1	0.2				kurrajong :	0.3	0.2	0.6	3.11	0	64626209	224.15	223.49	21.2
OF 1-6	Pit 1-6	HW 2-6	0.7				overland fl	0.3	0.3	0.6	2	0	91	222.7	221.45	89.3
OF2-6	HW 2-6	HW 9-1	0.3				kurrajong :	0.3	0.2	0.6	0.42	0	94	221.45	221.39	14.2
OF14-7	Pit1-7	Pit2-7	0.3				7.5 m road	0.3	0.15	0.4	1.22	100	6944971	225.38	224.975	33.1
OF2-5	Pit2-5	OF2-5	0.3				7.5 m road	0.3	0.15	0.4	2.79	100	52700451	226.83	225.81	36.5
OF1-5	Pit1-5	Pit1-7	0.2				10 m road	0.3	0.15	0.4	1.7	100	6944984	225.81	225.38	25.3
OF2-3	Pit2-3	OF2-3	0.2				7.5 m road	0.3	0.15	0.4	2.67	100	52700477	228.91	228.2	26.6
OF1-3	Pit1-3	Pit2-5	0.4				7.5 m road	0.3	0.15	0.4	2.59	100	52700515	228.2	226.83	52.9
OF2-2	Pit2-2	OF2-2	0.2				7.5 m road	0.3	0.15	0.4	2.71	100	52700528	231.05	230.2	31.4
OF79678	Pit1-2	Pit2-3	0.3				7.5 m road	0.3	0.15	0.4	2.68	100	52700545	230.2	228.91	48.2
OF89678	swale over s1	HW 9-1	1.2				kurrajong :	0.3	0.2	0.6	1.71	0	64626212	223.49	221.5	116.4

PIPE COVER DETAILS				
Name	Type	Dia (mm)	Safe Cover	Cover (m)
Pipe1-1	Concrete, i	450	0.6	0.91
Pipe2-1	Concrete, i	450	0.6	0.98
Pipe3-1	Concrete, i	450	0.6	0.98
Pipe4-1	Concrete, i	450	0.6	0.99
Pipe5-1	Concrete, i	600	0.6	0.8
PipeXX	Concrete, i	600	0.45	0.83
Pipe 6-1	Concrete, i	675	0.45	0.65
P2-7	Concrete, i	675	0.45	0.64
p3-7	Concrete, i	675	0.45	0.13
P4-7	Concrete, i	675	0.45	-0.73
Pipe1-4	uPVC, undi	154	0.5	0.71
Pipe2-4	uPVC, undi	242	0.5	0.62
Pipe3-4	uPVC, undi	303	0.5	0.56
Pipe4-4	uPVC, undi	303	0.5	0.56
Pipe5-4	uPVC, undi	303	0.5	0.56
Pipe6-4	uPVC, undi	386	0.5	0.48
Pipe7-4	uPVC, undi	386	0.5	0.51
Pipe8-4	uPVC, undi	386	0.5	1.18
Pipe9-4	Concrete, i	375	0.45	0.61
Pipe 7-1	Concrete, i	675	0.45	0.12
Pipe 8-1	Concrete, i	675	0.45	-0.73
PIPE 1-6	uPVC, not	303	0.3	-0.31
Pipe1-7	Concrete, i	600	0.45	0.89
Pip2-5	Concrete, i	450	0.6	0.89
Pipe1-5	Concrete, i	450	0.6	0.92
Pipe2-3	Concrete, i	450	0.6	0.88
Pipe1-3	Concrete, i	450	0.6	0.91
Pipe2-2	Concrete, i	450	0.6	0.88
Pipe1-2	Concrete, i	450	0.6	0.91

This model has no pipes with non-return valves

07 03 2023

R 0 0 0 C

0 0 R 0 0

207203

DRAINS results prepared from Version 2022.08.82.69.12475

20% ARI
PIT / NODE DETAILS

Name	Version 8					Overflow	Constraint
	Max HGL	Max Pond	Max Surf	Max Pond	Min		
	HGL	Flow Arriv	Flow	Flow	Freeboard	(cu m/s)	
		(cu m/s)	(cu m/s)	(cu m/s)	(m)		
Pit 1-1	231.04	0.26	0.013	1.23	0.044	Inlet Capacity	
Pit 2-1	230.81	0.013	1.23	0.013	0.013	Inlet Capacity	
Pit 3-1	229.15	0.015	1.05	0.015	0.015	Inlet Capacity	
Pit 4-1	227.81	0.018	0.99	0.018	0.018	Inlet Capacity	
Pit 5-1	224.9	0.013	0.91	0.013	0.013	Inlet Capacity	
Pit 6-1	224.07	225.06	0.123	0.9	0.01	Inlet Capacity	
Pit 7-1	223.96	225.05	0.135	0.9	1.01	Inlet Capacity	
Pit 8-1	222.81	0	0.97	0	0.97	Inlet Capacity	
Pit 9-1	222.07	0	0.29	0	0.29	Inlet Capacity	
Pit 10-1	221.83	0	0.23	0	0.23	Inlet Capacity	
Pit 11-1	229.27	0.061	0.44	0.061	0.44	Inlet Capacity	
Pit 12-1	228.16	0.023	0.44	0.023	0.44	Inlet Capacity	
Pit 13-1	227.36	0.095	0.44	0.095	0.44	Inlet Capacity	
Pit 14-1	226.8	0.076	0.6	0.076	0.6	Inlet Capacity	
Pit 15-1	226.48	0.093	0.52	0.093	0.52	Inlet Capacity	
Pit 16-1	225.62	0.075	0.56	0.075	0.56	Inlet Capacity	
Pit 17-1	224.88	0.063	0.52	0.063	0.52	Inlet Capacity	
Pit 18-1	224.05	0.066	0.55	0.066	0.55	Inlet Capacity	
Pit 19-1	223.68	0.138	0.47	0.138	0.47	Inlet Capacity	
Pit 20-1	223.04	0	0.45	0	0.45	Inlet Capacity	
Pit 21-1	222.27	0	0.08	0	0.08	Inlet Capacity	
Pit 22-1	221.95	0.355	0.01	0.355	0.01	Inlet Capacity	
Pit 23-1	222.89	0.182	0.01	0.182	0.01	Inlet Capacity	
Pit 24-1	222.62	0.257	0.01	0.257	0.01	Inlet Capacity	
Pit 25-1	224.17	0.216	1.21	0.216	1.21	Inlet Capacity	
Pit 26-1	223.8	0.173	1.03	0.173	1.03	Inlet Capacity	
Pit 27-1	225.53	0.213	0.26	0.213	0.26	Inlet Capacity	
Pit 28-1	228.14	0.074	0.77	0.074	0.77	Inlet Capacity	
Pit 29-1	227.98	0.07	0.22	0.07	0.22	Inlet Capacity	
Pit 30-1	229.79	0.117	1.26	0.117	1.26	Inlet Capacity	
Pit 31-1	229.3	0.056	0.9	0.056	0.9	Inlet Capacity	
Pit 32-1	223.49	0.101	0.01	0.101	0.01	Inlet Capacity	

SUB-CATCHMENT DETAILS

Name	Remaining EIA					PA	Due to Storm
	Flow Q	Max Q	Max Q	Tc	Tc		
	(cu m/s)	(cu m/s)	(cu m/s)	(min)	(min)	(min)	(min)
Cat 1-1	0.17	0.058	0.133	5	2	22 20% AEP, 1 hour burst, Storm 6	
Cat 2-1	0.008	0.003	0.005	5	2	5 20% AEP, 45 min burst, Storm 9	
Cat 3-1	0.009	0.004	0.005	5	2	5 20% AEP, 45 min burst, Storm 9	
Cat 4-1	0.011	0.004	0.006	5	2	5 20% AEP, 45 min burst, Storm 9	
Cat 5-1	0.014	0.006	0.008	5	2	5 20% AEP, 45 min burst, Storm 9	
Cat 6-1	0.102	0.022	0.08	5	2	22 20% AEP, 1 hour burst, Storm 6	
Cat 7-1	0.092	0.02	0.072	5	2	22 20% AEP, 1 hour burst, Storm 6	
Cat 8-1	0.038	0.014	0.026	5	2	5 20% AEP, 30 min burst, Storm 7	
Cat 9-1	0.038	0.014	0.026	5	2	5 20% AEP, 30 min burst, Storm 7	
Cat 10-1	0.038	0.014	0.026	5	2	5 20% AEP, 30 min burst, Storm 7	
Cat 11-1	0.038	0.014	0.026	5	2	5 20% AEP, 30 min burst, Storm 7	
Cat 12-1	0.038	0.014	0.026	5	2	5 20% AEP, 30 min burst, Storm 7	
Cat 13-1	0.038	0.014	0.026	5	2	5 20% AEP, 30 min burst, Storm 7	
Cat 14-1	0.038	0.014	0.026	5	2	5 20% AEP, 30 min burst, Storm 7	
Cat 15-1	0.038	0.014	0.026	5	2	5 20% AEP, 30 min burst, Storm 7	
Cat 16-1	0.146	0.042	0.123	5	5	10 20% AEP, 45 min burst, Storm 5	
Cat 17-1	0.111	0.028	0.143	5	2	5 20% AEP, 45 min burst, Storm 9	
Cat 18-1	0.102	0.022	0.08	5	2	22 20% AEP, 1 hour burst, Storm 6	
Cat 19-1	0.163	0.036	0.128	5	2	22 20% AEP, 1 hour burst, Storm 6	
Cat 20-1	0.148	0.031	0.112	5	2	22 20% AEP, 1 hour burst, Storm 6	
Cat 21-1	0.122	0.027	0.096	5	2	22 20% AEP, 1 hour burst, Storm 6	
Cat 22-1	0.102	0.022	0.08	5	2	22 20% AEP, 1 hour burst, Storm 6	
Cat 23-1	0.061	0.013	0.048	5	2	22 20% AEP, 1 hour burst, Storm 6	
Cat 24-1	0.071	0.016	0.056	5	2	22 20% AEP, 1 hour burst, Storm 6	

PIPE DETAILS

Name	Max V					Due to Storm
	Flow Q	Max Q	Max Q	HGL (m)	HGL (m)	
	(cu m/s)	(cu m/s)	(cu m/s)	(m)	(m)	
Pipe 1-1	0.127	1.44	230.889	230.815	20% AEP, 45 min burst, Storm 8	
Pipe 2-1	0.132	1.44	230.794	229.145	20% AEP, 45 min burst, Storm 5	
Pipe 3-1	0.326	2.24	229.088	227.805	20% AEP, 1 hour burst, Storm 6	
Pipe 4-1	0.552	3.47	227.15	224.901	20% AEP, 1 hour burst, Storm 6	
Pipe 5-1	0.861	3.21	224.856	224.071	20% AEP, 1 hour burst, Storm 8	
Pipe 6-1	0.323	1.88	223.986	223.959	20% AEP, 1 hour burst, Storm 8	
Pipe 7-1	0.606	2.2	223.983	223.041	20% AEP, 1 hour burst, Storm 6	
Pipe 8-1	0.584	2.63	223.883	222.512	20% AEP, 1 hour burst, Storm 6	
Pipe 9-1	0.556	2.3	223.512	222.071	20% AEP, 1 hour burst, Storm 6	
Pipe 10-1	0.562	2.2	223.259	221.837	20% AEP, 1 hour burst, Storm 6	
Pipe 11-1	0.037	1.97	228.837	228.164	20% AEP, 30 min burst, Storm 7	
Pipe 12-1	0.074	1.79	227.912	227.364	20% AEP, 30 min burst, Storm 7	
Pipe 13-1	0.111	1.72	227.134	226.805	20% AEP, 30 min burst, Storm 7	
Pipe 14-1	0.114	1.75	226.156	226.482	20% AEP, 30 min burst, Storm 10	
Pipe 15-1	0.157	2.25	226.381	225.617	20% AEP, 30 min burst, Storm 6	
Pipe 16-1	0.183	1.81	225.612	224.878	20% AEP, 30 min burst, Storm 10	
Pipe 17-1	0.22	2.06	224.831	224.052	20% AEP, 30 min burst, Storm 10	
Pipe 18-1	0.239	2.21	223.851	223.876	20% AEP, 30 min burst, Storm 10	
Pipe 19-1	0.298	2.69	223.345	223.041	20% AEP, 30 min burst, Storm 10	
Pipe 20-1	0.123	2.17	222.851	222.274	20% AEP, 1 hour burst, Storm 8	
Pipe 21-1	0.775	2.45	222.145	221.947	20% AEP, 1 hour burst, Storm 8	
Pipe 22-1	0.119	1.61	222.227	221.646	20% AEP, 45 min burst, Storm 4	
Pipe 23-1	0.133	1.2	224.075	223.959	20% AEP, 1 hour burst, Storm 6	
Pipe 24-1	0.142	0.91	225.594	225.531	20% AEP, 45 min burst, Storm 9	
Pipe 25-1	0.278	1.75	224.847	224.901	20% AEP, 45 min burst, Storm 8	
Pipe 26-1	0.122	0.77	228.014	227.958	20% AEP, 1 hour burst, Storm 6	
Pipe 27-1	0.222	1.4	227.834	227.805	20% AEP, 1 hour burst, Storm 6	
Pipe 28-1	0.103	1.31	226.671	226.302	20% AEP, 1 hour burst, Storm 6	
Pipe 29-1	0.174	1.27	229.184	229.145	20% AEP, 1 hour burst, Storm 6	

CHANNEL DETAILS

Name	Max V					Due to Storm
	Flow Q	Max Q	Max Q	Max V	Max V	
	(cu m/s)	(cu m/s)	(cu m/s)	(m/s)	(m/s)	

OVERFLOW ROUTE DETAILS


Name	Max Q					Due to Storm
	Flow Q	Max Q	Max Q	Max Q	Max Q	
	(cu m/s)	(cu m/s)	(cu m/s)	(cu m/s)	(cu m/s)	
OF 1-1	0.044	0.104	0.055	0.085	0.11	1.43 20% AEP, 1 hour burst, Storm 6
OF 2-1	0	0	0.768	0	0	0
OF 3-1	0	0	0.742	0	0	0
OF 4-1	0	0	0.738	0	0	0
OF 5-1	0	0	0.785	0	0	0
OF 6-1	0.01	0.01	0.434	0.055	0.01	1.59 20% AEP, 1 hour burst, Storm 6
OF 7-1	0	0	0.767	0	0	0
OF 8-1	0.001	0.001	0.82	0.004	0	2.02 0 20% AEP, 45 min burst, Storm 9
OF 9-1	0.001	0.001	0.737	0.005	0	2.02 0 20% AEP, 45 min burst, Storm 9
OF 10-1	0.001	0.001	0.705	0.005	0	2.02 0.1 20% AEP, 45 min burst, Storm 7
OF 11-1	0	0	0.761	0	0	0
OF 12-1	0.001	0.001	0.742	0.004	0	2.02 0 20% AEP, 45 min burst, Storm 9
OF 13-1	0.001	0.001	0.737	0.004	0	2.02 0 20% AEP, 45 min burst, Storm 9
OF 14-1	0.001	0.001	0.767	0.004	0	2.02 0 20% AEP, 45 min burst, Storm 9
OF 15-1	0.001	0.001	2.778	0.004	0	6.03 0.08 20% AEP, 45 min burst, Storm 9
OF 16-1	0.001	0.001	0.851	0.004	0	2.02 0.15 20% AEP, 45 min burst, Storm 7
OF 17-1	0.014	0.011	11.996	0.169	0	19.98 0.11 20% AEP, 45 min burst, Storm 5
OF 18-1	0.233	0.233	0.313	0.169	0.1	2.68 0.59 20% AEP, 45 min burst, Storm 5
OF 19-1	0	0.091	0.501	0.084	0.05	2.6 0.63 20% AEP, 1 hour burst, Storm 6
OF 20-1	0.027	0.174	0.757	0.093	0.14	3.18 1.52 20% AEP, 1 hour burst, Storm 8
OF 21-1	0.034	0.128	0.566	0.099	0.1	3.19 1.16 20% AEP, 1 hour burst, Storm 6
OF 22-1	0	0.101	0.741	0.088	0.1	2.78 1.33 20% AEP, 1 hour burst, Storm 6
OF 23-1	0	0.152	0.73	0.101	0.13	3.24 1.43 20% AEP, 45 min burst, Storm 7
OF 24-1	0	0.071	0.746	0.079	0.08	2.43 1.25 20% AEP, 1 hour burst, Storm 6
OF 25-1	0	0.121	0.742	0.095	0.11	3.03 1.38 20% AEP, 1 hour burst, Storm 6
swale over	0	0	0.632	0	0	0

DETENTION BASIN DETAILS

Name	Max V				
	Max V	Max V	Max V	Max V	Max V
	(m/s)	(m/s)	(m/s)	(m/s)	(m/s)

Run Log for stage 6_A.drn run at 13:40:42 on 22/12/2022 using version 2022.08.82.69.12475

No water upwelling from any pit.
Freeboard was less than 0.15m at Pit 1-6 - LARGE OVERLAND FLOW CATCHMENT NOW DOWNSTREAM IMPACT
Flows were safe in all overflow routes.



PLANS PREPARED BY

MM HYNDES BAILEY & Co.
REGISTERED SURVEYORS - TOWN PLANNING - CIVIL DESIGN
Surveying the Hunter since 1920



P:002 643247
P:002 2611M:SWILL:R:002 SW 2333

CLIENT



DRAINS RESULTS 20% AEP
STAGE 6
KURRAJONG ESTATE, SATUR

DESIGN:

M. COLE
R. JONES

DRAWN:

M. COLE
R. JONES

SCAL: 1:1000

RI: 1:1000

LGA: UPPER HUNTER

FILE: 207203_S6_DRAIN

SHEET: DRAIN_008

PLA: ISS: 00

A: ISS: 00 C: 00 CIL

S: 00 RMWA: 00 R: PDA: 00

C: I: 00 R: ALL: 00 M: 00 PDA: 00

07/03/2023

R: 00 C

00 R: 00

207203

DRAINS results prepared from Version 2022.08.8269.12475

1% AEP

PIT / NODE DETAILS

Name	Version 8		Min	Overflow	Constraint			
	Max HGL	Max Pond HGL						
Flow Ann/Volume (cum/s) (cum)								
(m)								
PIT-1-1	231.05	0.415	0.99	0.256	Inlet Capacity			
PIT-2-1	230.83	0.031	1.21	0	None			
PIT-3-1	229.93	0.037	0.27	0	None			
PIT-4-1	228.29	0.044	0	0.063	Outlet System			
PIT-5-1	225.66	0.149	0.15	0.014	Inlet Capacity			
PIT-6-1	225.07	0.264	0.9	0	0.014	Outlet System		
PIT-7-1	225.02	0.135	0.9	0	0.644	Outlet System		
PIT-7-2	223.39	0	0.09	None				
PIT-4-7	222.58	0	0	0	Outlet System			
HW9-1a	221.99	0	0	0				
PIT-1-4	229.34	0.121	0	0.052	Outlet System			
PIT-2-4	228.86	0.116	0	0.094	Outlet System			
PIT-3-4	227.91	0.237	0	0.128	Outlet System			
PIT-4-4	227.46	0.172	0	0.099	Outlet System			
PIT-5-4	227.08	0.237	0	0.145	Outlet System			
PIT-6-4	226.24	0.271	0	0.08	Outlet System			
PIT-7-4	225.45	0.24	0	0.172	Outlet System			
PIT-8-4	224.71	0.37	0	0.29	Outlet System			
PIT-9-4	224.37	0.54	0	0.385	Outlet System			
PIT-7-1	224.08	0	0	0	Outlet System			
PIT-8-1	222.71	0	0	0	Outlet System			
HW-9-1	222.01	1.82	0	0				
PIT-1-6	222.73	0.44	0	0.207	Outlet System			
HW-2-6	221.74	0.836	0	0				
PIT-7-1	225.41	1.365	0	1.018	Outlet System			
PIT-2-5	226.84	0.919	0	0.734	Outlet System			
PIT-1-5	226.02	1.026	0	1.097	Outlet System			
PIT-2-3	228.77	0.494	0.14	0.348	Inlet Capacity			
PIT-3-3	228.37	0.54	0	0.623	Outlet System			
PIT-2-2	230.64	0.563	0.41	0.236	Inlet Capacity			
PIT-1-2	230.29	0.354	0	0.272	Outlet System			
11	223.72	1.114						

SUB-CATCHMENT DETAILS

Name	Max Flow Q (cu.m/s)	EIA Max Q (cu.m/s)	Remaining EIA		RIA Tc (min)	PA Tc (min)	Due to Storm (min)
			Max Q	Tc			
Cat1-1/1	0.362	0.002	0.124	5	2	22	1% AEP, 30 min burst, Storm 6
Cat12-1	0.021	0.009	0.013	5	2	5	1% AEP, 10 min burst, Storm 7
Cat13-1	0.026	0.01	0.015	5	2	5	1% AEP, 10 min burst, Storm 7
Cat14-1	0.03	0.012	0.018	5	2	5	1% AEP, 10 min burst, Storm 7
Cat15-1	0.039	0.015	0.023	5	2	5	1% AEP, 10 min burst, Storm 7
Cat16-1	0.219	0.037	0.184	5	2	22	1% AEP, 30 min burst, Storm 6
Cat12-7	0.206	0.033	0.174	5	2	22	1% AEP, 30 min burst, Storm 6
Cat1-4	0.086	0.026	0.06	5	2	5	1% AEP, 10 min burst, Storm 7
Cat12-4	0.086	0.026	0.06	5	2	5	1% AEP, 10 min burst, Storm 7
Cat13-4	0.086	0.026	0.06	5	2	5	1% AEP, 10 min burst, Storm 7
Cat15-4	0.086	0.026	0.06	5	2	5	1% AEP, 10 min burst, Storm 7
Cat16-4	0.086	0.026	0.06	5	2	5	1% AEP, 10 min burst, Storm 7
Cat17-4	0.086	0.026	0.06	5	2	5	1% AEP, 10 min burst, Storm 7
Cat18-4	0.086	0.026	0.06	5	2	5	1% AEP, 10 min burst, Storm 7
Cat19-4	0.086	0.026	0.06	5	2	5	1% AEP, 10 min burst, Storm 7
Cat1-6	0.329	0.085	0.248	5	5	10	1% AEP, 20 min burst, Storm 4
Cat12-6	0.428	0.021	0.406	5	2	5	1% AEP, 10 min burst, Storm 7
Cat1-7	0.219	0.037	0.184	5	2	22	1% AEP, 30 min burst, Storm 6
Cat12-5	0.366	0.059	0.31	5	2	22	1% AEP, 30 min burst, Storm 6
Cat11-5	0.32	0.052	0.271	5	2	22	1% AEP, 30 min burst, Storm 6
Cat12-3	0.274	0.045	0.233	5	2	22	1% AEP, 30 min burst, Storm 6
Cat1-3	0.219	0.037	0.184	5	2	22	1% AEP, 30 min burst, Storm 6
Cat12-2	0.137	0.022	0.115	5	2	22	1% AEP, 30 min burst, Storm 6
Cat11-2	0.16	0.026	0.136	5	2	22	1% AEP, 30 min burst, Storm 6

PIPE DETAILS

Name	Max Q (cu.m/s)	Max V (m/s)	Max U/S (m/s)	Max D/S (m)	Due to Storm
Pipe1-1	0.127	1.41	230.889	230.852	1% AEP, 2 hour burst, Storm 2
Pipe2-1	0.147	1.49	230.807	229.926	1% AEP, 10 min burst, Storm 7
Pipe3-1	0.433	2.72	229.409	228.292	1% AEP, 10 min burst, Storm 7
Pipe4-1	0.588	3.7	227.676	225.665	1% AEP, 25 min burst, Storm 10
Pipe5-1	0.931	3.29	225.351	225.072	1% AEP, 10 min burst, Storm 4
PipeXX	0.419	1.46	225.024	225.021	1% AEP, 15 min burst, Storm 5
Pipe 6-1	0.966	2.7	224.589	224.081	1% AEP, 25 min burst, Storm 6
P2-7	0.921	2.79	223.986	223.39	1% AEP, 30 min burst, Storm 6
p3-7	0.921	2.57	223.39	222.581	1% AEP, 30 min burst, Storm 6
P4-7	0.921	2.75	222.145	221.986	1% AEP, 30 min burst, Storm 6
Pipe1-4	0.039	2.09	229.187	228.658	1% AEP, 30 min burst, Storm 6
Pipe2-4	0.083	1.79	228.199	227.907	1% AEP, 30 min burst, Storm 7
Pipe3-4	0.13	1.8	227.344	227.456	1% AEP, 30 min burst, Storm 8
Pipe4-4	0.146	2.03	227.198	227.082	1% AEP, 10 min burst, Storm 8
Pipe5-4	0.198	2.74	226.676	226.24	1% AEP, 5 min burst, Storm 1
Pipe6-4	0.318	2.72	225.919	225.489	1% AEP, 10 min burst, Storm 4
Pipe7-4	0.31	2.64	225.081	224.709	1% AEP, 10 min burst, Storm 7
Pipe8-4	0.312	2.87	224.327	224.371	1% AEP, 25 min burst, Storm 7
Pipe9-4	0.379	3.45	224.219	224.081	1% AEP, 10 min burst, Storm 6
Pipe 7-1	1.069	2.99	223.738	222.707	1% AEP, 30 min burst, Storm 1
Pipe 8-1	1.069	3.09	222.214	222.014	1% AEP, 30 min burst, Storm 1
Pipe 1-6	0.117	1.64	222.304	221.74	1% AEP, 20 min burst, Storm 4
Pipe1-7	0.331	1.17	225.057	225.021	1% AEP, 20 min burst, Storm 1
Pipe1-5	0.254	1.6	226.21	226.017	1% AEP, 30 min burst, Storm 1
Pipe1-5	0.326	2.05	225.69	225.665	1% AEP, 20 min burst, Storm 6
Pipe2-3	0.196	1.23	228.454	228.369	1% AEP, 30 min burst, Storm 1
Pipe1-3	0.231	1.54	228.309	228.292	1% AEP, 45 min burst, Storm 8
Pipe2-2	0.157	0.99	230.352	230.288	1% AEP, 30 min burst, Storm 6
Pipe1-2	0.285	1.79	229.968	229.926	1% AEP, 25 min burst, Storm 6

CHANNEL DETAILS

Name	Max Q (cu.m/s)	Max V (m/s)	Due to Storm

OVERFLOW ROUTE DETAILS

Name	Max Q (cu.m/s)	Max Q/D (1/s/ft)	Max D (m)	Max D/V	Max Width (m)	Max V (m/s)	Due to Storm
OF1-1	0.256	0.392	1.092	0.121	0.22	4.33	1.8 1% AEP, 30 min burst, Storm 6
OF2-1	0	0	1.139	0	0	0	0
OF3-1	0	0	1.149	0	0	0	0
OF4-1	0.061	0.061	1.143	0.07	0.08	2.11	1.21 1% AEP, 30 min burst, Storm 8
OF5-1	0.014	0.014	1.205	0.038	0.04	0.96	0.98 1% AEP, 30 min burst, Storm 1
OF5ag	0.014	0.014	1.682	0.269	0	9.71	0.01 1% AEP, 25 min burst, Storm 10
OF6-1	0.644	0.643	1.559	0.236	0.27	2.94	1.5 1% AEP, 30 min burst, Storm 6
OF1-4	0.052	0.052	1.441	0.063	0.03	2.25	0.83 1% AEP, 10 min burst, Storm 9
OF2-4	0.094	0.094	1.505	0.075	0.04	2.3	0.74 1% AEP, 10 min burst, Storm 4
OF3-4	0.128	0.128	1.439	0.075	0.06	2.3	0.99 1% AEP, 10 min burst, Storm 4
OF4-4	0.099	0.099	1.552	0.081	0.05	2.32	0.77 1% AEP, 10 min burst, Storm 4
OF5-4	0.145	0.145	1.514	0.081	0.07	2.32	1.28 1% AEP, 10 min burst, Storm 4
OF6-4	0.08	0.08	1.505	0.087	0.04	2.35	0.7 1% AEP, 10 min burst, Storm 4
OF7-4	0.172	0.172	1.559	0.087	0.08	2.35	1.34 1% AEP, 10 min burst, Storm 4
OF8-4	0.29	0.29	2.778	0.126	0.05	7.01	0.76 1% AEP, 10 min burst, Storm 4
OF9785	0.385	0.385	1.535	0.158	0.17	2.63	1.35 1% AEP, 10 min burst, Storm 7
OF1-6	0.207	0.209	13.996	0.29	0.01	30.04	0.36 1% AEP, 20 min burst, Storm 4
OF2-6	0.6	0.6	0.639	0.29	0.23	3.16	0.8 1% AEP, 20 min burst, Storm 4
OF1-7	1.018	1.224	1.402	0.204	0.34	6.84	1.71 1% AEP, 30 min burst, Storm 1
OF2-5	0.734	1.053	1.147	0.183	0.34	6.31	2.07 1% AEP, 30 min burst, Storm 1
OF1-5	1.097	1.325	1.47	0.183	0.37	8.2	1.94 1% AEP, 30 min burst, Storm 1
OF2-3	0.348	0.576	1.147	0.143	0.25	5.3	1.75 1% AEP, 30 min burst, Storm 1
OF1-3	0.623	0.967	1.154	0.166	0.36	5.89	2.2 1% AEP, 30 min burst, Storm 1
OF2-2	0.236	0.395	1.155	0.124	0.21	4.53	1.68 1% AEP, 30 min burst, Storm 6
OF9786	0.272	0.545	1.149	0.14	0.25	5.22	1.81 1% AEP, 30 min burst, Storm 1
swale over	0.775	0.775	1.285	0.225	0.32	2.9	1.4 1% AEP, 30 min burst, Storm 1

DETENTION BASIN DETAILS


Name	Max WL	Max Vol	Max Q	Max Q	Max Q
	Total		Low Level	High Level	

Run Log for stage 6_a.drn run at 16:10:08 on 22/12/2022 using version 2022.08.8269.12475

Upwelling occurred at: PIT-4, PIT-6, PIT-8, PIT-10, PIT-12, PIT-14, PIT-16, PIT-18, PIT-20, PIT-22, PIT-24, PIT-26, PIT-28, PIT-30, PIT-32, PIT-34, PIT-36, PIT-38, PIT-40, PIT-42, PIT-44, PIT-46, PIT-48, PIT-50, PIT-52, PIT-54, PIT-56, PIT-58, PIT-60, PIT-62, PIT-64, PIT-66, PIT-68, PIT-70, PIT-72, PIT-74, PIT-76, PIT-78, PIT-80, PIT-82, PIT-84, PIT-86, PIT-88, PIT-90, PIT-92, PIT-94, PIT-96, PIT-98, PIT-100

Freeboard was less than 0.15m at PIT-2-3, PIT-2-5, PIT-2-7, PIT-7-1, PIT-1-6, PIT-2-4, PIT-3-4, PIT-4-4, PIT-5-4, PIT-6-4, PIT-7-4, PIT-8-4, PIT-9-4, PIT-10-4, PIT-11-4, PIT-12-4, PIT-13-4, PIT-14-4, PIT-15-4, PIT-16-4, PIT-17-4, PIT-18-4, PIT-19-4, PIT-20-4, PIT-21-4, PIT-22-4, PIT-23-4, PIT-24-4, PIT-25-4, PIT-26-4, PIT-27-4, PIT-28-4, PIT-29-4, PIT-30-4, PIT-31-4, PIT-32-4, PIT-33-4, PIT-34-4, PIT-35-4, PIT-36-4, PIT-37-4, PIT-38-4, PIT-39-4, PIT-40-4, PIT-41-4, PIT-42-4, PIT-43-4, PIT-44-4, PIT-45-4, PIT-46-4, PIT-47-4, PIT-48-4, PIT-49-4, PIT-50-4, PIT-51-4, PIT-52-4, PIT-53-4, PIT-54-4, PIT-55-4, PIT-56-4, PIT-57-4, PIT-58-4, PIT-59-4, PIT-60-4, PIT-61-4, PIT-62-4, PIT-63-4, PIT-64-4, PIT-65-4, PIT-66-4, PIT-67-4, PIT-68-4, PIT-69-4, PIT-70-4, PIT-71-4, PIT-72-4, PIT-73-4, PIT-74-4, PIT-75-4, PIT-76-4, PIT-77-4, PIT-78-4, PIT-79-4, PIT-80-4, PIT-81-4, PIT-82-4, PIT-83-4, PIT-84-4, PIT-85-4, PIT-86-4, PIT-87-4, PIT-88-4, PIT-89-4, PIT-90-4, PIT-91-4, PIT-92-4, PIT-93-4, PIT-94-4, PIT-95-4, PIT-96-4, PIT-97-4, PIT-98-4, PIT-99-4, PIT-100-4


Flows were safe in all overflow routes.



PLANS PREPARED BY

MM HYNDES BAILEY & Co.
REGISTERED SURVEYORS - TOWN PLANNING - CIVIL DESIGN
Surveying the Hunter since 1920

P002 6:43247
IP: 26:10:SW:LL:R:SW 2333



CLIENT



DRAINS RESULTS 1% AEP
STAGE 6
KURRAJONG ESTATE, SATUR

DESIGN:

M. COLE
R. JONES

DRAWN:

M. COLE
R. JONES

SCAL 1:1000

RI 1:1000 AL DRAW 1:1000 SI 1:1000 A1

LGA: UPPER HUNTER

FILE:207203_S6_DRAIN

SHEET: DRAIN_009

PLA 1:1000 ISS 1:1000


A ISS 1:1000 C 1:1000 CIL

S 1:1000 RMWA 1:1000 R 1:1000 PDA 1:1000

C I 1:1000 R ALL 1:1000 M 1:1000 PDA 1:1000

Appendix B

PHOTOLOG

	Plate 1 Description: Site observation, looking towards the north from BH01 Date: 14/03/2025
	Plate 2 Description: Site observation, looking towards the east from BH01 Date: 14/03/2025

**Plate 3**

Description:
Soil
encountered in
BH01

Date: 14/03/2025

**Plate 4**

Description:
Soil
encountered in
BH02

Date: 14/03/2025



Plate 5

Description:
Soil
encountered in
BH03

Date: 14/03/2025



Plate 6

Description:
Soil
encountered in
BH04

Date: 14/03/2025



Plate 7

Description:
Soil
encountered in
BH05

Date: 14/03/2025



Plate 8

Description:
Soil
encountered in
BH06

Date: 14/03/2025



Plate 9

Description:
Soil
encountered in
BH08

Date: 14/03/2025



Plate 10

Description:
Soil
encountered in
BH09

Date: 14/03/2025

**Plate 11**


Description:
Soil
encountered in
BH10

Date: 14/03/2025

**Plate 12**

Description:
Soil
encountered in
BH11

Date: 14/03/2025

	Plate 13 Description: Site observation, looking towards the east from BH12 Date: 14/03/2025
	Plate 14 Description: Site observation, looking towards the south from BH12 Date: 14/03/2025

 14 Mar 2025 at 12:48:57 pm 267° W 4 Cockatoo Cl Scone NSW 2337 Australia EP4090	Plate 15 Description: Site observation, looking towards the west from BH12 Date: 14/03/2025
 14 Mar 2025 at 12:49:02 pm 0° N 4 Cockatoo Cl Scone NSW 2337 Australia EP4090	Plate 16 Description: Site observation, looking towards the north from BH12 Date: 14/03/2025

	Plate 17 Description: Soil encountered in BH13 Date: 19/03/2025
	Plate 18 Description: Site observation, looking towards the north from BH14 Date: 19/03/2025


	Plate 19 Description: Site observation, looking towards the east from BH14 Date: 19/03/2025
	Plate 20 Description: Site observation, looking towards the south BH14 Date: 19/03/2025

	Plate 21 Description: Site observation, looking towards the west from BH14 Date: 19/03/2025
	Plate 22 Description: Soil encountered in BH14 Date: 19/03/2025



Plate 23

Description:
Soil
encountered in
BH15

Date: 19/03/2025



Plate 24

Description:
Soil
encountered in
BH16

Date: 19/03/2025



Plate 25

Description:

Soil
encountered in
BH17

Date: 19/03/2025




Plate 26


Description:

Soil
encountered in
BH18

Date: 19/03/2025

 19 Mar 2025 at 10:06:16 am 186° S 4 Cockatoo CI Scone NSW 2337 Australia EP4090	Plate 27 Description: Site observation, looking towards the south from BH19 Date: 19/03/2025
 19 Mar 2025 at 10:06:18 am 277° W 4 Cockatoo CI Scone NSW 2337 Australia EP4090	Plate 28 Description: Site observation, looking towards the west from BH19 Date: 19/03/2025

 19 Mar 2025 at 10:06:21 am 356° N 4 Cockatoo Cl Scone NSW 2337 Australia EP4090	Plate 29 Description: Site observation, looking towards the north from BH19 Date: 19/03/2025
 19 Mar 2025 at 10:29:54 am 201° S 35-37 Ibis Pl Scone NSW 2337 Australia EP4090 BH19	Plate 30 Description: Soil encountered in BH19 Date: 19/03/2025

	Plate 31 Description: Soil encountered in BH20 Date: 19/03/2025
	Plate 32 Description: Soil encountered in BH21 Date: 19/03/2025


Appendix C

GEOTECHNICAL INVESTIGATION LOCATIONS



Legend:

- Borehole (BH) Locations
- Site Boundary




Appendix D

BOREHOLE LOGS


CLAYS




CLAY



silty CLAY



sandy CLAY




gravelly CLAY


SILTS



SILT



clayey SILT



sandy SILT




gravelly SILT


SANDS




SAND



clayey SAND



silty SAND




gravelly SAND

GRAVELS




GRAVEL



clayey GRAVEL



silty GRAVEL



sandy GRAVEL

SEDIMENTARY ROCK



SANDSTONE



SILTSTONE




SHALE



CONGLOMERATE

FILL



FILL




CONCRETE




ASPHALT


GROUNDWATER WELL SYMBOLS




WELL SCREEN



CASING – filter pack



CASING – backfill



CASING – bentonite seal



CASING – grout seal




BACKFILL

OTHER



TOPSOIL – sandy SILT



TOPSOIL – highly organic

Remarks:

Engineering Log - Borehole

Client		McCloy Group Pty Ltd				Project No.		EP4090															
Project		Kurrajong Estate Stage 6				Logged By		JA															
Location		Ibis Place, Scone NSW 2337				Checked By		OP															
Started Drilling		14.3.25		Northing		6452708.00		Slope		90°		Equipment		Ute Drilling Rig									
Completed Drilling		14.3.25		Easting		295352.00		Bearing		---		Ground Level											
DRILLING		MATERIAL DESCRIPTION										TESTING, SAMPLING & OTHER INFORMATION											
Method		Water		RL (m)		Depth (m)		Graphic Log		Classification		Description of Soil (soil type: plasticity/grainsize, colour and other components)		Moisture Condition		Consistency		Tests DCP Results (blows/100mm)		Samples		Additional Comments (material origin, pocket penetrometer values, investigation observations)	
AD/V		Not Encountered				CL-CI		TOPSOIL: Silty CLAY: low to medium plasticity, black		<PL		VSt		5		TOPSOIL							
						CI-CH		Silty CLAY: medium to high plasticity, black						6									
						0.70m: Colour change to brown		1.50m: Colour change to brown and white, with fine to medium grained sand, fine to medium grained, sub-angular gravel						<PL				St to VSt		6		RESIDUAL SOIL	
																				6			
																				6			
																				6			
																				7			
																				6			
																				5			
																				5			
																				6			
																				4			
																				4			
																				5			
																				5			
																				4			
																				8			
																				9			
																				7			
																				9			
10																							
10																							
10																							
10																							
2.00m: Colour change to grey and brown		<<PL																					
3												Target depth											
Remarks:																							

EP LUB 05.GLB Log CW NON-CORED BOREHOLE LOG EP4090 MCCLOY SCONE KURRAJONG STAGE 6.GPJ <<DrawingFile>> 01/04/2025 12:27 10:05:00.09 Developed by Datigel

Remarks:

Engineering Log - Borehole

Client		McCloy Group Pty Ltd				Project No.		EP4090																																			
Project		Kurrajong Estate Stage 6				Logged By		JA																																			
Location		Ibis Place, Scone NSW 2337				Checked By		OP																																			
Started Drilling		14.3.25		Northing		6452767.00		Slope		90°		Equipment		Ute Drilling Rig																													
Completed Drilling		14.3.25		Easting		295381.00		Bearing		---		Ground Level																															
DRILLING		MATERIAL DESCRIPTION										TESTING, SAMPLING & OTHER INFORMATION																															
Method		Water		RL (m)		Depth (m)		Graphic Log		Classification		Description of Soil (soil type: plasticity/grainsize, colour and other components)		Moisture Condition		Consistency		Tests DCP Results (blows/100mm)		Samples		Additional Comments (material origin, pocket penetrometer values, investigation observations)																					
AD/V		Not Encountered								CL- CI		TOPSOIL: Silty CLAY: low to medium plasticity, black				F		2				TOPSOIL																					
												Silty CLAY: medium to high plasticity, black						2				RESIDUAL SOIL																					
												0.70m: Colour change to brown		<PL		St to VSt		2																									
																		2																									
																		2						3																			
																		2						3																			
																		3						3																			
																		4						4																			
																		5						5																			
																		3						4																			
																		5						5																			
																		5						5																			
																		4						5																			
																		4						4																			
																		4						6																			
																		5						6																			
																		6						6																			
																		6						6																			
																		8						10																			
																		9																									

Remarks:

Remarks:

Engineering Log - Borehole

Client		McCloy Group Pty Ltd				Project No.		EP4090												
Project		Kurrajong Estate Stage 6				Logged By		JA												
Location		Ibis Place, Scone NSW 2337				Checked By		OP												
Started Drilling		14.3.25		Northing		6452844.00		Slope 90°												
Completed Drilling		14.3.25		Easting		295410.00		Bearing ---												
						Equipment		Ute Drilling Rig												
						Ground Level														
DRILLING		MATERIAL DESCRIPTION						TESTING, SAMPLING & OTHER INFORMATION												
Method	Water	RL (m)	Depth (m)	Graphic Log	Classification	Description of Soil (soil type: plasticity/grainsize, colour and other components)	Moisture Condition	Consistency	Tests DCP Results (blows/100mm)	Samples	Additional Comments (material origin, pocket penetrometer values, investigation observations)									
AD/V	Not Encountered		1 2 3	CL-CI CI-CH	TOPSOIL: Silty CLAY: low to medium plasticity, black		<PL	F	2		TOPSOIL									
					Silty CLAY: medium to high plasticity, black				2											
									2											
					0.60m: Colour change to brown				2											
									2											
									4											
									5											
									5											
									6											
									6											
									6											
									6											
									5											
					5															
					5															
					5															
					5															
					5															
					4															
					6															
					5															
					4															
					5															
					6															
					6															
					5															
					6															
					5															
					9															
					Borehole BH07 Terminated at 3.00 m										Target depth					
					Remarks:															

[illegible]

Remarks:

Remarks:

Remarks:

Engineering Log - Borehole

Client		McCloy Group Pty Ltd				Project No.		EP4090										
Project		Kurrajong Estate Stage 6				Logged By		JA										
Location		Ibis Place, Scone NSW 2337				Checked By		OP										
Started Drilling		14.3.25		Northing		6453027.00		Slope 90°										
Completed Drilling		14.3.25		Easting		295451.00		Bearing ---										
						Equipment		Ute Drilling Rig										
						Ground Level												
DRILLING		MATERIAL DESCRIPTION						TESTING, SAMPLING & OTHER INFORMATION										
Method	Water	RL (m)	Depth (m)	Graphic Log	Classification	Description of Soil (soil type: plasticity/grainsize, colour and other components)	Moisture Condition	Consistency	Tests DCP Results (blows/100mm)	Samples	Additional Comments (material origin, pocket penetrometer values, investigation observations)							
AD/V	Not Encountered		1		CL-CI	TOPSOIL: Silty CLAY: low to medium plasticity, black	<PL	St	3	U50	TOPSOIL							
					CI-CH	Silty CLAY: medium to high plasticity, black		St	3		RESIDUAL SOIL							
								VSt	4									
									6									
									6									
									5									
									5									
									7									
									6									
									6									
									6									
									6									
									5									
									6									
									6									
					6													
					5													
					5													
					7													
					6													
					6													
					6													
					7													
					6													
					6													
					6													
					6													
					3													
					Borehole BH12 Terminated at 3.00 m											Target depth		
					Remarks:													

EP_LUB 05.GLB Log CW NON-CORED BOREHOLE LOG EP4090 MCCLOY SCONE KURRAJONG STAGE 6.GPJ <<DrawingFile>> 01/04/2025 12:27 10:05:00.09 Developed by Datigel

Remarks:

Remarks:

Engineering Log - Borehole

Client		McCloy Group Pty Ltd				Project No.		EP4090				
Project		Kurrajong Estate Stage 6				Logged By		JA				
Location		Ibis Place, Scone NSW 2337				Checked By		OP				
Started Drilling		19.3.25	Northing		6452858.00	Slope		90°	Equipment	Ute Drilling Rig		
Completed Drilling		19.3.25	Easting		295498.00	Bearing		---	Ground Level			
DRILLING		MATERIAL DESCRIPTION					TESTING, SAMPLING & OTHER INFORMATION					
Method	Water	RL (m)	Depth (m)	Graphic Log	Classification	Description of Soil (soil type: plasticity/grainsize, colour and other components)	Moisture Condition	Consistency	Tests DCP Results (blows/100mm)	Samples	Additional Comments (material origin, pocket penetrometer values, investigation observations)	
AD/V	Not Encountered		1		CL- CI	TOPSOIL: Silty CLAY: low to medium plasticity, black	<PL	VSt and St	6		TOPSOIL	
					CI- CH	Silty CLAY: medium to high plasticity, black			5		RESIDUAL SOIL	
											3	
											5	
						0.40m: Colour change to brown					6	
											5	
											5	
											4	
											4	
											5	
											5	
											4	
											5	
											3	
						1.30m: Colour change to brown and white, with fine grained, sub-angular gravel					4	
											3	
											4	
											4	
						1.60m: with fine to mediumgrained sand					4	
											4	
											4	
											4	
											4	
											7	
											10	
											14	
											8	
											8	
			9									
			3									
Borehole BH15 Terminated at 3.00 m												
Target depth												
Remarks:												

Remarks:

Remarks:

Engineering Log - Borehole

Client		McCloy Group Pty Ltd				Project No.		EP4090										
Project		Kurrajong Estate Stage 6				Logged By		JA										
Location		Ibis Place, Scone NSW 2337				Checked By		OP										
Started Drilling		19.3.25		Northing		6452765.00		Slope 90°										
Completed Drilling		19.3.25		Easting		295476.00		Bearing ---										
						Equipment		Ute Drilling Rig										
						Ground Level												
DRILLING		MATERIAL DESCRIPTION					TESTING, SAMPLING & OTHER INFORMATION											
Method	Water	RL (m)	Depth (m)	Graphic Log	Classification	Description of Soil (soil type: plasticity/grainsize, colour and other components)	Moisture Condition	Consistency	Tests DCP Results (blows/100mm)	Samples	Additional Comments (material origin, pocket penetrometer values, investigation observations)							
AD/V	Not Encountered		1		CL-CI	TOPSOIL: Silty CLAY: low to medium plasticity, black	<PL	VSt	5		TOPSOIL							
					CI-CH	Silty CLAY: medium to high plasticity, black			4		RESIDUAL SOIL							
									4									
									3									
									3									
									2									
									3									
									3									
									2									
									3									
									3									
									3									
									4									
									4									
									4									
									4									
									4									
									5									
									6									
									7									
									8									
									8									
									6									
									7									
									8									
									3									Target depth
					Remarks:													

Remarks:

Engineering Log - Borehole

Client		McCloy Group Pty Ltd				Project No.		EP4090									
Project		Kurrajong Estate Stage 6				Logged By		JA									
Location		Ibis Place, Scone NSW 2337				Checked By		OP									
Started Drilling		19.3.25		Northing		6452699.00		Slope 90°									
Completed Drilling		19.3.25		Easting		295460.00		Bearing ---									
						Equipment		Ute Drilling Rig									
						Ground Level											
DRILLING		MATERIAL DESCRIPTION					TESTING, SAMPLING & OTHER INFORMATION										
Method	Water	RL (m)	Depth (m)	Graphic Log	Classification	Description of Soil (soil type: plasticity/grainsize, colour and other components)	Moisture Condition	Consistency	Tests DCP Results (blows/100mm)	Samples	Additional Comments (material origin, pocket penetrometer values, investigation observations)						
AD/V	Not Encountered		1		CL-CI	TOPSOIL: Silty CLAY: low to medium plasticity, black	<PL	St	3		TOPSOIL						
					CI-CH	Silty CLAY: medium to high plasticity, black		F	2		RESIDUAL SOIL						
									2								
									1								
									2								
									2								
									2								
									2								
									4								
									3								
									4								
									5								
									6								
									4								
									4								
									3								
									6								
									7								
									8								
									5								
									8								
									8								
									7								
									8								
									8								
									7								
									8								
									3								
									2								
									1								
			0.60m: Colour change to brown														
			1.00m: Colour change to black and white, with fine grained, sub-rounded gravel														
			2.10m: Colour change to brown and white														
			Borehole BH20 Terminated at 3.00 m														
Remarks:																	

Remarks:

Appendix E

LABORATORY TEST RESULTS

Material Test Report

Report Number: NEWC25296-1
Issue Number: 1
Date Issued: 01/04/2025
Client: EP Risk Management
PO Box 57, Lochinvar NSW 2321
Project Number: NEWC25296
Project Name: Kurrajong Estate Stage 6
Project Location: Ibis Place, Scone NSW
Client Reference: EP4090
Work Request: 4466
Dates Tested: 17/03/2025 - 20/03/2025
Location: Kurrajong Estate Stage 6 - Lot Classification



Newcastle Laboratory
16 Callistemon Close Warabrook NSW 2304
Phone: 0438 938 932
Email: Newcastle Laboratory



Accredited for compliance with ISO/IEC 17025 - Testing

Approved Signatory: Raphael Kirby-Faust
Geotechnician
Laboratory Accreditation Number: 431

Shrink Swell Index AS 1289 7.1.1 & 2.1.1					
Sample Number	NEWC4466A	NEWC4466B	NEWC4466C	NEWC4466D	NEWC4466E
Date Sampled	01/04/2025	01/04/2025	01/04/2025	01/04/2025	01/04/2025
Date Tested	17/03/2025	17/03/2025	17/03/2025	17/03/2025	17/03/2025
Material Source	**	**	**	**	**
Sample Location	BH03 (0.6 - 1.10)	BH06 (0.50 - 1.00)	BH09 (0.50 - 1.00)	BH12 (1.00 - 1.50)	BH13 (0.60 - 1.10)
Inert Material Estimate (%)	0	2	0	0	0
Pocket Penetrometer before (kPa)	600+	460	600	600+	600+
Pocket Penetrometer after (kPa)	180	280	200	230	200
Shrinkage Moisture Content (%)	28.8	30.7	26.8	24.7	28.2
Shrinkage (%)	6.0	7.6	5.5	6.4	6.6
Swell Moisture Content Before (%)	27.2	33.7	28.7	26.6	28.3
Swell Moisture Content After (%)	40.5	40.8	38.9	35.9	35.9
Swell (%)	7.1	5.2	7.9	8.2	5.7
Shrink Swell Index Iss (%)	5.3	5.7	5.2	5.8	5.3
Visual Description	Silty CLAY. Some Gravel	Silty CLAY	Silty CLAY with some Gravel	Silty CLAY	Silty CLAY (Brown)
Cracking	SC	MC	SC	SC	SC
Crumbling	No	**	No	**	No
Remarks	**	**	**	Silty CLAY	**

Shrink Swell Index (Iss) reported as the percentage vertical strain per pF change in suction.
Cracking Terminology: UC Uncracked, SC Slightly Cracked, MC Moderately Cracked, HC Highly Cracked, FR Fragmented.
NATA Accreditation does not cover the performance of pocket penetrometer readings.

Material Test Report

Report Number: NEWC25296-1
Issue Number: 1
Date Issued: 01/04/2025
Client: EP Risk Management
PO Box 57, Lochinvar NSW 2321
Project Number: NEWC25296
Project Name: Kurrajong Estate Stage 6
Project Location: Ibis Place, Scone NSW
Client Reference: EP4090
Work Request: 4466
Dates Tested: 17/03/2025 - 20/03/2025
Location: Kurrajong Estate Stage 6 - Lot Classification



Newcastle Laboratory
16 Callistemon Close Warabrook NSW 2304
Phone: 0438 938 932
Email: Newcastle Laboratory



Accredited for compliance with ISO/IEC 17025 - Testing

Approved Signatory: Raphael Kirby-Faust
Geotechnician

Laboratory Accreditation Number: 431

Shrink Swell Index AS 1289 7.1.1 & 2.1.1

Sample Number	NEWC4466F	NEWC4466G			
Date Sampled	01/04/2025	01/04/2025			
Date Tested	20/03/2025	20/03/2025			
Material Source	**	**			
Sample Location	BH16 (0.60 - 1.10)	BH19 (0.60 - 1.10)			
Inert Material Estimate (%)	0	0			
Pocket Penetrometer before (kPa)	+600	+600			
Pocket Penetrometer after (kPa)	230	240			
Shrinkage Moisture Content (%)	31.2	31.9			
Shrinkage (%)	6.9	6.6			
Swell Moisture Content Before (%)	30.0	30.8			
Swell Moisture Content After (%)	37.5	39.6			
Swell (%)	8.9	6.0			
Shrink Swell Index Iss (%)	6.3	5.3			
Visual Description	Silty CLAY (Brown)	Silty CLAY (Brown)			
Cracking	SC	SC			
Crumbling	No	No			
Remarks	**	**			

Shrink Swell Index (Iss) reported as the percentage vertical strain per pF change in suction.

Cracking Terminology: UC Uncracked, SC Slightly Cracked, MC Moderately Cracked, HC Highly Cracked, FR Fragmented.

NATA Accreditation does not cover the performance of pocket penetrometer readings.

Material Test Report

Report Number: NEWC25289-1
Issue Number: 1
Date Issued: 02/04/2025
Client: Lee Lesley (COD ONLY)
155 Queen Street, Muswellbrook NSW 2333
Contact: Le Lesley
Project Number: NEWC25289
Project Name: Lot 607 - Kurrajong Estate
Project Location: Scone NSW
Work Request: 4382
Dates Tested: 24/03/2025 - 24/03/2025
Location: Lot Testing



Newcastle Laboratory
16 Callistemon Close Warabrook NSW 2304
Phone: 0438 938 932
Email: Newcastle Laboratory



Accredited for compliance with ISO/IEC 17025 - Testing

Approved Signatory: Raphael Kirby-Faust
Geotechnician

Laboratory Accreditation Number: 431

Shrink Swell Index AS 1289 7.1.1 & 2.1.1

Sample Number	NEWC4382A				
Date Sampled	25/03/2025				
Date Tested	24/03/2025				
Material Source	**				
Sample Location	Lot 607 - BH1 (0.7 - 1m)				
Inert Material Estimate (%)	0				
Pocket Penetrometer before (kPa)	600+				
Pocket Penetrometer after (kPa)	210				
Shrinkage Moisture Content (%)	28.4				
Shrinkage (%)	5.1				
Swell Moisture Content Before (%)	28.9				
Swell Moisture Content After (%)	31.1				
Swell (%)	6.3				
Shrink Swell Index Iss (%)	4.6				
Visual Description	silty CLAY (brown)				
Cracking	MC				
Crumbling	No				
Remarks	**				

Shrink Swell Index (Iss) reported as the percentage vertical strain per pF change in suction.

Cracking Terminology: UC Uncracked, SC Slightly Cracked, MC Moderately Cracked, HC Highly Cracked, FR Fragmented.

NATA Accreditation does not cover the performance of pocket penetrometer readings.

Appendix F

FOUNDATION MAINTENANCE AND FOOTING
PERFORMANCE

Foundation Maintenance and Footing Performance: A Homeowner's Guide

Buildings can and often do move. This movement can be up, down, lateral or rotational. The fundamental cause of movement in buildings can usually be related to one or more problems in the foundation soil. It is important for the homeowner to identify the soil type in order to ascertain the measures that should be put in place in order to ensure that problems in the foundation soil can be prevented, thus protecting against building movement.

This Building Technology File is designed to identify causes of soil-related building movement, and to suggest methods of prevention of resultant cracking in buildings.

Soil Types

The types of soils usually present under the topsoil in land zoned for residential buildings can be split into two approximate groups – granular and clay. Quite often, foundation soil is a mixture of both types. The general problems associated with soils having granular content are usually caused by erosion. Clay soils are subject to saturation and swell/shrink problems.

Classifications for a given area can generally be obtained by application to the local authority, but these are sometimes unreliable and if there is doubt, a geotechnical report should be commissioned. As most buildings suffering movement problems are founded on clay soils, there is an emphasis on classification of soils according to the amount of swell and shrinkage they experience with variations of water content. The table below is Table 2.1 from AS 2870, the Residential Slab and Footing Code.

Causes of Movement

Settlement due to construction

There are two types of settlement that occur as a result of construction:

- Immediate settlement occurs when a building is first placed on its foundation soil, as a result of compaction of the soil under the weight of the structure. The cohesive quality of clay soil mitigates against this, but granular (particularly sandy) soil is susceptible.
- Consolidation settlement is a feature of clay soil and may take place because of the expulsion of moisture from the soil or because of the soil's lack of resistance to local compressive or shear stresses. This will usually take place during the first few months after construction, but has been known to take many years in exceptional cases.

These problems are the province of the builder and should be taken into consideration as part of the preparation of the site for construction. Building Technology File 19 (BTF 19) deals with these problems.

Erosion

All soils are prone to erosion, but sandy soil is particularly susceptible to being washed away. Even clay with a sand component of say 10% or more can suffer from erosion.

Saturation

This is particularly a problem in clay soils. Saturation creates a bog-like suspension of the soil that causes it to lose virtually all of its bearing capacity. To a lesser degree, sand is affected by saturation because saturated sand may undergo a reduction in volume – particularly imported sand fill for bedding and blinding layers. However, this usually occurs as immediate settlement and should normally be the province of the builder.

Seasonal swelling and shrinkage of soil

All clays react to the presence of water by slowly absorbing it, making the soil increase in volume (see table below). The degree of increase varies considerably between different clays, as does the degree of decrease during the subsequent drying out caused by fair weather periods. Because of the low absorption and expulsion rate, this phenomenon will not usually be noticeable unless there are prolonged rainy or dry periods, usually of weeks or months, depending on the land and soil characteristics.

The swelling of soil creates an upward force on the footings of the building, and shrinkage creates subsidence that takes away the support needed by the footing to retain equilibrium.

Shear failure

This phenomenon occurs when the foundation soil does not have sufficient strength to support the weight of the footing. There are two major post-construction causes:

- Significant load increase.
- Reduction of lateral support of the soil under the footing due to erosion or excavation.
- In clay soil, shear failure can be caused by saturation of the soil adjacent to or under the footing.

GENERAL DEFINITIONS OF SITE CLASSES

Class	Foundation
A	Most sand and rock sites with little or no ground movement from moisture changes
S	Slightly reactive clay sites with only slight ground movement from moisture changes
M	Moderately reactive clay or silt sites, which can experience moderate ground movement from moisture changes
H	Highly reactive clay sites, which can experience high ground movement from moisture changes
E	Extremely reactive sites, which can experience extreme ground movement from moisture changes
A to P	Filled sites
P	Sites which include soft soils, such as soft clay or silt or loose sands; landslip; mine subsidence; collapsing soils; soils subject to erosion; reactive sites subject to abnormal moisture conditions or sites which cannot be classified otherwise

Tree root growth

Trees and shrubs that are allowed to grow in the vicinity of footings can cause foundation soil movement in two ways:

- Roots that grow under footings may increase in cross-sectional size, exerting upward pressure on footings.
- Roots in the vicinity of footings will absorb much of the moisture in the foundation soil, causing shrinkage or subsidence.

Unevenness of Movement

The types of ground movement described above usually occur unevenly throughout the building's foundation soil. Settlement due to construction tends to be uneven because of:

- Differing compaction of foundation soil prior to construction.
- Differing moisture content of foundation soil prior to construction.

Movement due to non-construction causes is usually more uneven still. Erosion can undermine a footing that traverses the flow or can create the conditions for shear failure by eroding soil adjacent to a footing that runs in the same direction as the flow.

Saturation of clay foundation soil may occur where subfloor walls create a dam that makes water pond. It can also occur wherever there is a source of water near footings in clay soil. This leads to a severe reduction in the strength of the soil which may create local shear failure.

Seasonal swelling and shrinkage of clay soil affects the perimeter of the building first, then gradually spreads to the interior. The swelling process will usually begin at the uphill extreme of the building, or on the weather side where the land is flat. Swelling gradually reaches the interior soil as absorption continues. Shrinkage usually begins where the sun's heat is greatest.

Effects of Uneven Soil Movement on Structures

Erosion and saturation

Erosion removes the support from under footings, tending to create subsidence of the part of the structure under which it occurs. Brickwork walls will resist the stress created by this removal of support by bridging the gap or cantilevering until the bricks or the mortar bedding fail. Older masonry has little resistance. Evidence of failure varies according to circumstances and symptoms may include:

- Step cracking in the mortar beds in the body of the wall or above/below openings such as doors or windows.
- Vertical cracking in the bricks (usually but not necessarily in line with the vertical beds or perpend).

Isolated piers affected by erosion or saturation of foundations will eventually lose contact with the bearers they support and may tilt or fall over. The floors that have lost this support will become bouncy, sometimes rattling ornaments etc.

Seasonal swelling/shrinkage in clay

Swelling foundation soil due to rainy periods first lifts the most exposed extremities of the footing system, then the remainder of the perimeter footings while gradually permeating inside the building footprint to lift internal footings. This swelling first tends to create a dish effect, because the external footings are pushed higher than the internal ones.

The first noticeable symptom may be that the floor appears slightly dished. This is often accompanied by some doors binding on the floor or the door head, together with some cracking of cornice mitres. In buildings with timber flooring supported by bearers and joists, the floor can be bouncy. Externally there may be visible dishing of the hip or ridge lines.

As the moisture absorption process completes its journey to the innermost areas of the building, the internal footings will rise. If the spread of moisture is roughly even, it may be that the symptoms will temporarily disappear, but it is more likely that swelling will be uneven, creating a difference rather than a disappearance in symptoms. In buildings with timber flooring supported by bearers and joists, the isolated piers will rise more easily than the strip footings or piers under walls, creating noticeable doming of flooring.



As the weather pattern changes and the soil begins to dry out, the external footings will be first affected, beginning with the locations where the sun's effect is strongest. This has the effect of lowering the external footings. The doming is accentuated and cracking reduces or disappears where it occurred because of dishing, but other cracks open up. The roof lines may become convex.

Doming and dishing are also affected by weather in other ways. In areas where warm, wet summers and cooler dry winters prevail, water migration tends to be toward the interior and doming will be accentuated, whereas where summers are dry and winters are cold and wet, migration tends to be toward the exterior and the underlying propensity is toward dishing.

Movement caused by tree roots

In general, growing roots will exert an upward pressure on footings, whereas soil subject to drying because of tree or shrub roots will tend to remove support from under footings by inducing shrinkage.

Complications caused by the structure itself

Most forces that the soil causes to be exerted on structures are vertical – i.e. either up or down. However, because these forces are seldom spread evenly around the footings, and because the building resists uneven movement because of its rigidity, forces are exerted from one part of the building to another. The net result of all these forces is usually rotational. This resultant force often complicates the diagnosis because the visible symptoms do not simply reflect the original cause. A common symptom is binding of doors on the vertical member of the frame.

Effects on full masonry structures

Brickwork will resist cracking where it can. It will attempt to span areas that lose support because of subsided foundations or raised points. It is therefore usual to see cracking at weak points, such as openings for windows or doors.

In the event of construction settlement, cracking will usually remain unchanged after the process of settlement has ceased.

With local shear or erosion, cracking will usually continue to develop until the original cause has been remedied, or until the subsidence has completely neutralised the affected portion of footing and the structure has stabilised on other footings that remain effective.

In the case of swell/shrink effects, the brickwork will in some cases return to its original position after completion of a cycle, however it is more likely that the rotational effect will not be exactly reversed, and it is also usual that brickwork will settle in its new position and will resist the forces trying to return it to its original position. This means that in a case where swelling takes place after construction and cracking occurs, the cracking is likely to at least partly remain after the shrink segment of the cycle is complete. Thus, each time the cycle is repeated, the likelihood is that the cracking will become wider until the sections of brickwork become virtually independent.

With repeated cycles, once the cracking is established, if there is no other complication, it is normal for the incidence of cracking to stabilise, as the building has the articulation it needs to cope with the problem. This is by no means always the case, however, and monitoring of cracks in walls and floors should always be treated seriously.

Upheaval caused by growth of tree roots under footings is not a simple vertical shear stress. There is a tendency for the root to also exert lateral forces that attempt to separate sections of brickwork after initial cracking has occurred.

The normal structural arrangement is that the inner leaf of brickwork in the external walls and at least some of the internal walls (depending on the roof type) comprise the load-bearing structure on which any upper floors, ceilings and the roof are supported. In these cases, it is internally visible cracking that should be the main focus of attention, however there are a few examples of dwellings whose external leaf of masonry plays some supporting role, so this should be checked if there is any doubt. In any case, externally visible cracking is important as a guide to stresses on the structure generally, and it should also be remembered that the external walls must be capable of supporting themselves.

Effects on framed structures

Timber or steel framed buildings are less likely to exhibit cracking due to swell/shrink than masonry buildings because of their flexibility. Also, the doming/dishing effects tend to be lower because of the lighter weight of walls. The main risks to framed buildings are encountered because of the isolated pier footings used under walls. Where erosion or saturation cause a footing to fall away, this can double the span which a wall must bridge. This additional stress can create cracking in wall linings, particularly where there is a weak point in the structure caused by a door or window opening. It is, however, unlikely that framed structures will be so stressed as to suffer serious damage without first exhibiting some or all of the above symptoms for a considerable period. The same warning period should apply in the case of upheaval. It should be noted, however, that where framed buildings are supported by strip footings there is only one leaf of brickwork and therefore the externally visible walls are the supporting structure for the building. In this case, the subfloor masonry walls can be expected to behave as full brickwork walls.

Effects on brick veneer structures

Because the load-bearing structure of a brick veneer building is the frame that makes up the interior leaf of the external walls plus perhaps the internal walls, depending on the type of roof, the building can be expected to behave as a framed structure, except that the external masonry will behave in a similar way to the external leaf of a full masonry structure.

Water Service and Drainage

Where a water service pipe, a sewer or stormwater drainage pipe is in the vicinity of a building, a water leak can cause erosion, swelling or saturation of susceptible soil. Even a minuscule leak can be enough to saturate a clay foundation. A leaking tap near a building can have the same effect. In addition, trenches containing pipes can become watercourses even though backfilled, particularly where broken rubble is used as fill. Water that runs along these trenches can be responsible for serious erosion, interstrata seepage into subfloor areas and saturation.

Pipe leakage and trench water flows also encourage tree and shrub roots to the source of water, complicating and exacerbating the problem. Poor roof plumbing can result in large volumes of rainwater being concentrated in a small area of soil:

- Incorrect falls in roof guttering may result in overflows, as may gutters blocked with leaves etc.

- Corroded guttering or downpipes can spill water to ground.
- Downpipes not positively connected to a proper stormwater collection system will direct a concentration of water to soil that is directly adjacent to footings, sometimes causing large-scale problems such as erosion, saturation and migration of water under the building.

Seriousness of Cracking

In general, most cracking found in masonry walls is a cosmetic nuisance only and can be kept in repair or even ignored. The table below is a reproduction of Table C1 of AS 2870.

AS 2870 also publishes figures relating to cracking in concrete floors, however because wall cracking will usually reach the critical point significantly earlier than cracking in slabs, this table is not reproduced here.

Prevention/Cure

Plumbing

Where building movement is caused by water service, roof plumbing, sewer or stormwater failure, the remedy is to repair the problem. It is prudent, however, to consider also rerouting pipes away from the building where possible, and relocating taps to positions where any leakage will not direct water to the building vicinity. Even where gully traps are present, there is sometimes sufficient spill to create erosion or saturation, particularly in modern installations using smaller diameter PVC fixtures. Indeed, some gully traps are not situated directly under the taps that are installed to charge them, with the result that water from the tap may enter the backfilled trench that houses the sewer piping. If the trench has been poorly backfilled, the water will either pond or flow along the bottom of the trench. As these trenches usually run alongside the footings and can be at a similar depth, it is not hard to see how any water that is thus directed into a trench can easily affect the foundation's ability to support footings or even gain entry to the subfloor area.

Ground drainage

In all soils there is the capacity for water to travel on the surface and below it. Surface water flows can be established by inspection during and after heavy or prolonged rain. If necessary, a grated drain system connected to the stormwater collection system is usually an easy solution.

It is, however, sometimes necessary when attempting to prevent water migration that testing be carried out to establish watertable height and subsoil water flows. This subject is referred to in BTF 19 and may properly be regarded as an area for an expert consultant.


Protection of the building perimeter

It is essential to remember that the soil that affects footings extends well beyond the actual building line. Watering of garden plants, shrubs and trees causes some of the most serious water problems.

For this reason, particularly where problems exist or are likely to occur, it is recommended that an apron of paving be installed around as much of the building perimeter as necessary. This paving

CLASSIFICATION OF DAMAGE WITH REFERENCE TO WALLS		
Description of typical damage and required repair	Approximate crack width limit (see Note 3)	Damage category
Hairline cracks	<0.1 mm	0
Fine cracks which do not need repair	<1 mm	1
Cracks noticeable but easily filled. Doors and windows stick slightly	<5 mm	2
Cracks can be repaired and possibly a small amount of wall will need to be replaced. Doors and windows stick. Service pipes can fracture. Weathertightness often impaired	5–15 mm (or a number of cracks 3 mm or more in one group)	3
Extensive repair work involving breaking-out and replacing sections of walls, especially over doors and windows. Window and door frames distort. Walls lean or bulge noticeably, some loss of bearing in beams. Service pipes disrupted	15–25 mm but also depend on number of cracks	4

Gardens for a reactive site



- Water that is transmitted into masonry, metal or timber building elements causes damage and/or decay to those elements.
- High subfloor humidity and moisture content create an ideal environment for various pests, including termites and spiders.
- Where high moisture levels are transmitted to the flooring and walls, an increase in the dust mite count can ensue within the living areas. Dust mites, as well as dampness in general, can be a health hazard to inhabitants, particularly those who are abnormally susceptible to respiratory ailments.

The garden

The ideal vegetation layout is to have lawn or plants that require only light watering immediately adjacent to the drainage or paving edge, then more demanding plants, shrubs and trees spread out in that order.

Overwatering due to misuse of automatic watering systems is a common cause of saturation and water migration under footings. If it is necessary to use these systems, it is important to remove garden beds to a completely safe distance from buildings.

Existing trees

Where a tree is causing a problem of soil drying or there is the existence or threat of upheaval of footings, if the offending roots are subsidiary and their removal will not significantly damage the tree, they should be severed and a concrete or metal barrier placed vertically in the soil to prevent future root growth in the direction of the building. If it is not possible to remove the relevant roots without damage to the tree, an application to remove the tree should be made to the local authority. A prudent plan is to transplant likely offenders before they become a problem.

Information on trees, plants and shrubs

State departments overseeing agriculture can give information regarding root patterns, volume of water needed and safe distance from buildings of most species. Botanic gardens are also sources of information. For information on plant roots and drains, see Building Technology File 17.

Excavation

Excavation around footings must be properly engineered. Soil supporting footings can only be safely excavated at an angle that allows the soil under the footing to remain stable. This angle is called the angle of repose (or friction) and varies significantly between soil types and conditions. Removal of soil within the angle of repose will cause subsidence.

Remediation

Where erosion has occurred that has washed away soil adjacent to footings, soil of the same classification should be introduced and compacted to the same density. Where footings have been undermined, augmentation or other specialist work may be required. Remediation of footings and foundations is generally the realm of a specialist consultant.

Where isolated footings rise and fall because of swell/shrink effect, the homeowner may be tempted to alleviate floor bounce by filling the gap that has appeared between the bearer and the pier with blocking. The danger here is that when the next swell segment of the cycle occurs, the extra blocking will push the floor up into an accentuated dome and may also cause local shear failure in the soil. If it is necessary to use blocking, it should be by a pair of fine wedges and monitoring should be carried out fortnightly.

This BTF was prepared by John Lewer FAIB, MIAMA, Partner, Construction Diagnosis.

should extend outwards a minimum of 900 mm (more in highly reactive soil) and should have a minimum fall away from the building of 1:60. The finished paving should be no less than 100 mm below brick vent bases.

It is prudent to relocate drainage pipes away from this paving, if possible, to avoid complications from future leakage. If this is not practical, earthenware pipes should be replaced by PVC and backfilling should be of the same soil type as the surrounding soil and compacted to the same density.

Except in areas where freezing of water is an issue, it is wise to remove taps in the building area and relocate them well away from the building – preferably not uphill from it (see BTF 19).

It may be desirable to install a grated drain at the outside edge of the paving on the uphill side of the building. If subsoil drainage is needed this can be installed under the surface drain.

Condensation

In buildings with a subfloor void such as where bearers and joists support flooring, insufficient ventilation creates ideal conditions for condensation, particularly where there is little clearance between the floor and the ground. Condensation adds to the moisture already present in the subfloor and significantly slows the process of drying out. Installation of an adequate subfloor ventilation system, either natural or mechanical, is desirable.

Warning: Although this Building Technology File deals with cracking in buildings, it should be said that subfloor moisture can result in the development of other problems, notably:

The information in this and other issues in the series was derived from various sources and was believed to be correct when published.

The information is advisory. It is provided in good faith and not claimed to be an exhaustive treatment of the relevant subject.

Further professional advice needs to be obtained before taking any action based on the information provided.

Distributed by

CSIRO PUBLISHING PO Box 1139, Collingwood 3066, Australia

Freecall 1800 645 051 Tel (03) 9662 7666 Fax (03) 9662 7555 www.publish.csiro.au

Email: publishing.sales@csiro.au

© CSIRO 2003. Unauthorised copying of this Building Technology file is prohibited

